


"SITE INFORMATION													
*SURVEY DATE:	June 26, 2	2013	45640 301st Street										
*SURVEYOR:	Jim Stone		*COUNTY:	Clay									
			*CITY:	Wako	Wakonda								
				•									
LOCATION DESCRIPTION:	LOCATION DESCRIPTION: From Vermillion, the intersection of South Dakota Highway 50 bi-pass and												
South Dakota Highway 19, North 15 miles to 302 nd Street, turn left (West) 6 miles to 456 th Ave., turn right													
(North) 1 mile to 301st Street, turn right (East) about 1/3 mile, on the left (North) side.													
LEGAL DESCRIPTION: <u>E ½, SW ¼, 23 – 95 – 53 Star Twp.</u>													
*QUARTER 1: SW ²	1/4	(OWNER NAME:	Charle	s T.	& Sı	ızan	ne S	tock	land			
*QUARTER 2:			OWNER NAME: Charles T. & Suzanne Stockland OWNER ADDRESS: 45327 299th Street										
*TOWNSHIP: Sta	ar		OWNER CITY: Irene										
*RANGE: 53	3	O	OWNER STATE: South Dakota										
*SECTION: 23	}		OWNER ZIP:										
ACRES: 76.6		QUAD NAME:											
OWNER CODE 1: P													
OWNER CODE 2:													
OWNER CODE 3:													
HISTORIC SIGNIFICAN	ICE												
*DOE:			REGISTER NAME:										
*DOE: *DOE DATE:			MULTIPLE PROPERTY NAME:										
REASON INELIGIBLE:						_							
				C	ATE	GOR	RY:						
NOMINATION STATUS:			SIGNIFICANCE LEVEL 1: N S L										
DATE LIST	ED:		SIGNI	FICANC	E LE	VEL	2:	N	S	L			
REFERENCE NUMBI	ER:												
HISTORIC DISTRICT RATIN	NG: C or	NC	CRITE	RIA 1:	Α	В	С	D					
PERIO	OD:		CRITE	RIA 2:	Α	В	С	D					
			CRITE	RIA 3:	Α	В	С	D					
			CRITE	RIA 4:	Α	В	С	D					
SIGNIFICANCE NOTES:													


STRUCTURE DETAILS



SHPO ID:		<u>_</u>									
*PROPERTY NAME:											
OTHER NAME:											
CURRENT FUNCTION:	Calving barn	FOUNDATION:	Poured concrete								
		_	Asphalt shingles over								
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	cedar shingles								
HISTORIC FUNCTION:	Livestock barn	_ ROOF SHAPE:	Gambrel roof								
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing								
		STYLE:	Gambrel roof barn								
OCCUPIED:	Yes	TYPE:	Livestock barn								
	Yes with		2x6 studs, 1x6 #106								
ACCESSIBLE:	permission	WALLS:	drop siding								
STORIES:	2	SIGNIFICANT PERSON:	William F. Mayer								
*DATE OF CONSTRUCTION:	1920's Cl	JLTURAL AFFILIATION:	?								
ALTERED/MOVED NOTES: Original site. All evidence of horse stalls and or milk cow stanchions has											
been removed. Asphalt shingles have been installed over cedar shingles on the roof. Cupola is gone.											
•		<u> </u>									
INTERIOR NOTES: One row	of 6x6 posts, and 6x6 b	eam support the 2x10 joists for	the hayloft floor. The								
		olid wall, 14' from the North wa									
	to ground level. It is 31	' – 6" from the ground up to the	peak of the roof in this								
area.											
		siding. Rafters are 2x6's with a									
	ace on each hip 2' O. C.	Asphalt shingles over cedar s	shingles. Windows are								
8" x 10" four light.											
*PHYSICAL NOTES: Barn is	s in fair condition.										
*IITM ZONE:		*RESTRICTED: Y	or N								
			/1 14								
*UTM NORTHING:											











Jim Stone PHOTOGRAPHER: **ROLL NUMBER:** DATE OF PHOTO: June 26, 2013 **PHOTO NUMBER:**

CAMERA DIRECTION: Looking NE, SW corner

PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 26, 2013

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 26, 2013 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 26, 2013 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 26, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking NW, 6x6 post, 6x6 beam, 2x10 joists, some evidence of

CAMERA DIRECTION: horse stalls.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 26, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking NW, 6x6 posts and 6x6 beam

CAMERA DIRECTION: supporting hip.






PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 26, 2013

ROLL NUMBER: PHOTO NUMBER:

Hayloft, looking NE, 6x6 posts, 6x6 beam supporting hip, note 2x6 CAMERA DIRECTION: brace at hip, 4' O. C.





© Farm & Home Publishers Ltd. 39 CLAY CO., SD



HISTORY

This farm located in the SW ¼ in Section 23, Star Township Clay County was homesteaded by Joseph Coppoc.

The 1894, 1901 and 1912 Clay County Atlas lists William F. Mayer as the owner.

The 1924 Clay County Atlas lists Lewis W. Mayer as the owner.

The 1937 Clay County Atlas lists L. McDonald as the owner and F. L. Mayer as the operator.

The 1948 and 1956 Clay County atlas lists F. L. McDonald as the owner.

