

#### SITE INFORMATION

May 24, 2012 \*SURVEY DATE: Correction Nov. 7, 2013 \*SURVEYOR: Jim Stone

\*ADDRESS: 30222 458<sup>th</sup> Ave.

\*COUNTY: Clay \*CITY: Wakonda

LOCATION DESCRIPTION: From the intersection of South Dakota Highway 50 bi-pass and South Dakota Highway 19, North 15 miles, turn left (West) on 302<sup>nd</sup> Street 4 miles , turn left North) on 458<sup>th</sup> Ave. about <sup>1</sup>/<sub>2</sub> mile, turn left (East) into driveway.

LEGAL DESCRIPTION: Skonhovd Tract 1, NW ¼, 31 – 95 – 52 Riverside Twp.

									James			leen	Don	ahu	e	
*QUARTER 1:	<u> </u>	W 1/	4					NAME:								
*QUARTER 2:						OWI		DRESS:			Wak	onda	a Her	itage	e Mai	lor
*TOWNSHIP:	<u> </u>	ivers	side					R CITY:								
_		-				C		STATE:	-		ota					
*SECTION:		31					OWN	ER ZIP:	57073							
ACRES:		9.61				QUAD	NAME:									
OWNER CODE 1:	P	2														
OWNER CODE 2:		-														
OWNER CODE 3:	F	S	L	Р												
	IFIC	?ΔN	ICE													
*DOE:																
*DOE DATE:					MUL		ROPERT	Y N/	AME:	-						
REASON INELIGIE	LE:															
											GOF					
NOMINATIO								SIGNI	FICANO	ELE	EVEL	. 1:	Ν	-	L	
DATE LISTED:					SIGNI	FICANO	ELE	EVEL	. 2:	Ν	S	L				
REFERENCE	E NU	IMB	ER:													
HISTORIC DISTRIC	CT R		۱G:	С	or NC			CRITI	ERIA 1:	Α	В	С	D			
	Ρ	ERIC	)D:					CRITI	ERIA 2:	Α	В	С	D			
								CRITI	ERIA 3:	Α	в	С	D			
								CRITI	ERIA 4:	Α	В	С	D			
SIGNIFICANCE NO	TES	i: _														



STRUCTURE DETAILS				
SHPO ID:		_		
*PROPERTY NAME:				
OTHER NAME:				
<b>CURRENT FUNCTION:</b>	Vacant	FOUNDATI	ION:	Poured concrete
CURRENT SUBFUNCTION:	Storage	ROOF MATER	IAL:	Steel
HISTORIC FUNCTION:	Livestock barn	ROOF SHA	APE:	Gambrel
HISTORIC SUBFUNCTION:	Hay and grain storage	STRUCTURAL SYST	EM:	Balloon framing
		STY	YLE:	Gambrel roof barn
OCCUPIED:	Yes	TY	YPE:	Livestock barn
ACCESSIBLE:	Yes with permission	WAI	LLS:	2x6 and 2x8, sheathing & ½"x6" cedar lap siding
STORIES:	2	SIGNIFICANT PERSON:	N	/illiam W. Schmidt
*DATE OF CONSTRUCTION:	1915 to 1925 CU	ILTURAL AFFILIATION:		?

ALTERED/MOVED NOTES: Original site. Milk cow stanchions have been removed. Roof has been covered with steel roofing. The West row of 6x6 posts and 6x8 beam have been removed, but are still in in the barn.

INTERIOR NOTES: Four rows 6x6 posts with 6x8 beams. 2x10 floor joists. Two rows 6x6 posts and 6x6 beams supporting the roof hip in the hayloft. Posts in the hayloft are 12' O.C. from the North and South gable ends with 10' O. C. in the center. Two 2x10's brace from the 6x6 rafter behind each post

down to the bottom of each 6x6 post.

OTHER NOTES: <u>8"x10" four light windows over 8"x10" four light window, double hung for ventilation.</u>

2x6 walls 13'-6" high on the East and West walls with horizontal sheathing. 2x8 walls 16' high on the


gable ends with 2x6 wall above to rafters with diagonal sheathing. ½"x6" cedar lap siding on all walls. Two 6x8x22' timbers with a scarf joint in the center make each beam on each of the four (40') long beams. Metal cupola.

\*PHYSICAL NOTES: <u>Barn is in very good condition. Very well built barn. Needs painting and Patrick</u> Donahue said it will be painted this summer.

*UTM ZONE:	*RESTRICTED:	Y	or	Ν
<b>*UTM EASTING:</b>				
*UTM NORTHING:				
-				



#### SKETCH MAP



\* = REQUIRED FIELD

3





PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	May 24, 2012	PHOTO NUMBER:	1
		CAMERA DIRECTION:	Looking NW, SE corner





 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 May 24, 2012
 PHOTO NUMBER:
 2

 CAMERA DIRECTION:
 Looking NE, SW corner





 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 May 24, 2012
 PHOTO NUMBER:
 3


 CAMERA DIRECTION:
 Looking SE, NW corner





PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	May 24, 2012	PHOTO NUMBER:	4
_		CAMERA DIRECTION:	Looking SW, NE corner






PHOTOGRAPHER: \_\_\_\_\_ DATE OF PHOTO:

Jim Stone May 24, 2012

ROLL NUMBER:	
PHOTO NUMBER:	
	Firs
CAMERA DIRECTION	6x6

5 First floor, looking North, 6x6 posts & 6x8 beam





PHOTOGRAPHER:Jim StoneDATE OF PHOTO:May 24, 2012

ROLL NUMBER:	
PHOTO NUMBER:	6
	First floor, looking
	South, 6x6 posts & 6x8
CAMERA DIRECTION:	beam

\* = REQUIRED FIELD






PHOTOGRAPHER:Jim StoneDATE OF PHOTO:May 24, 2012

ROLL NUMBER:	
PHOTO NUMBER:	7
CAMERA DIRECTION:	First floor, looking West into original horse stall





 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 May 24, 2012
 PHOTO NUMBER:
 8

 Hayloft, looking North,<br/>6x6 post, 6x6 rafter &<br/>rafter bracing
 6x6 rafter &<br/>rafter bracing





PHOTOGRAPHER: Jim Stone DATE OF PHOTO: May 24, 2012 ROLL NUMBER: PHOTO NUMBER:

9 Hayloft, granary in NW corner, with roof over granary

CAMERA DIRECTION: granary






PHOTOGRAPHER: Jim Stone DATE OF PHOTO: May 24, 2012

**ROLL NUMBER:** PHOTO NUMBER: 10 Hayloft, looking NE, two 2x10's bracing from 6x6 rafter to bottom of 6x6

CAMERA DIRECTION: post





35

G Farm & Home Publishers, Ltd.

\* = REQUIRED FIELD

1

4

CLAY CO., SD



# History

This farm located in the NW ¼ of Section 31 in Riverside Township, Clay County was homesteaded by George Harlocker.

1894 and 1901 Clay County Atlas lists A. Hallam as the owner.

The 1912, 1924 and 1937 Clay County Atlas lists William W. Schmidt as the owner. The 1924 Clay County Atlas also lists the farm as "West Riverside Farm"

The 1948 and 1956 Clay County Atlas lists D. F. Collins as the owner.