

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



SITE INFORMATION

*SURVEY DATE: May 11, 2013 *ADDRESS: 29896 463rd Ave.
*SURVEYOR: Jim Stone *COUNTY: Clay
*CITY: Centerville

LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50 and South Dakota Highway 19 Intersection, 17 miles north to 300th Street, turn right, East about 1 mile to 463rd Ave, turn left, North about 1-1/4 miles, on the right, East side of 463rd Ave.

LEGAL DESCRIPTION: W1/2, SW1/4, 12-95-52 Riverside Twp

*QUARTER 1: SE 1/4 OWNER NAME: Duane E. & Mary A. Auch
*QUARTER 2: _____ OWNER ADDRESS: 29896 463 Ave.
*TOWNSHIP: Riverside OWNER CITY: Centerville, South Dakota
*RANGE: 52 OWNER STATE: South Dakota
*SECTION: 12 OWNER ZIP: 57014
ACRES: 83.34 QUAD NAME: _____
OWNER CODE 1: P
OWNER CODE 2:
OWNER CODE 3:

HISTORIC SIGNIFICANCE

*DOE: _____ REGISTER NAME: _____
*DOE DATE: _____ MULTIPLE PROPERTY NAME: _____
REASON INELIGIBLE: _____

NOMINATION STATUS: _____ CATEGORY: _____
DATE LISTED: _____ SIGNIFICANCE LEVEL 1: N S L
REFERENCE NUMBER: _____ SIGNIFICANCE LEVEL 2: N S L
HISTORIC DISTRICT RATING: C or NC CRITERIA 1: A B C D
PERIOD: _____ CRITERIA 2: A B C D
CRITERIA 3: A B C D
CRITERIA 4: A B C D

SIGNIFICANCE NOTES: Owned by the same family for over 70 years.

STRUCTURE DETAILS

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



SHPO ID: _____
 *PROPERTY NAME: _____
 OTHER NAME: _____

CURRENT FUNCTION: Vacant FOUNDATION: Poured concrete
 CURRENT SUBFUNCTION: Vacant ROOF MATERIAL: Steel roofing
 HISTORIC FUNCTION: Home ROOF SHAPE: Gable roof
 HISTORIC SUBFUNCTION: Home STRUCTURAL SYSTEM: Balloon framing

OCCUPIED: Yes STYLE: Western feeder barn
 TYPE: Livestock barn
2x4& 2x6studs, 1x6 drop siding, 1/2"x6" cedar lap siding and covered partially with steel
 ACCESSIBLE: Yes with permission WALLS: _____

STORIES: 2 SIGNIFICANT PERSON: Andres J. Sjuberg
Changed last name to Shuberg
 *DATE OF CONSTRUCTION: Before 1908 CULTURAL AFFILIATION: Swedish

ALTERED/MOVED NOTES: Roof has steel roofing and walls have been covered with some steel roofing over the 1/2 x 6 cedar lap siding over 1x6 drop siding. Interior 2x4 wall was removed and supported by 4x6 posts and 4x6 beam 2' south, lean-to removed from the west side.

INTERIOR NOTES: Three rows of 4x6 posts support 4x6 beams, which support 2x6 floor joists.

OTHER NOTES: _____
Six 8x10 four light windows, steel roofing on some walls

*PHYSICAL NOTES: barn is in fair condition. *RESTRICTED: Y or N
 *UTM EASTING: _____
 *UTM NORTHING: _____

SITE INFORMATION

*UTM EASTING: _____
 *UTM NORTHING: _____

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: May 10, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: May 10, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: May 10, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: May 10, 2013

ROLL NUMBER: _____
PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: May 10, 2013

ROLL NUMBER: 5
PHOTO NUMBER: 5

CAMERA DIRECTION: First floor, looking NW ,
4x6 posts and 4x6 beam,
2x6 floor joists




PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: May 10, 2013

ROLL NUMBER: 6
PHOTO NUMBER: 6

CAMERA DIRECTION: First floor, looking NW,
2x4 wall cutout, post and
beam installed 2' south

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: May 10, 2013

ROLL NUMBER: 7
PHOTO NUMBER: 7

**Looking NW, stair railing
& looking down stairs
from second floor**

CAMERA DIRECTION: _____



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: May 10, 2013

ROLL NUMBER: 8
PHOTO NUMBER: 8

**Hayloft, looking west,
west gable end**

CAMERA DIRECTION: _____

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**




PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: May 10, 2013

ROLL NUMBER: 9
PHOTO NUMBER: 9
CAMERA DIRECTION: Hayloft, looking SE, 7'
wall in hayloft, 2x4 studs,
2x6 rafters

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



T-95-N RIVERSIDE DIRECTORY R-52-W



* = REQUIRED FIELD

HISTORY

1870 Homesteaded by A. J. Sjoberg, he received his land patent in March 1877

1884 Clay County Map shows owner A. J. Sjuberg.

1894 Clay County Atlas lists A. J. Sjoberg as the owner.

1901 and 1912 Clay County Atlas lists Anders J. Shuberg as the owner.

**1924 Clay County Atlas lists John Shuberg as the owner. (was called the “Hillside Farm”
at that time)**

1937,1940 and 1956 Clay County Atlas lists H. L. Paulson as the owner.

See letter on next page

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM



*This picture is probably taken about 1906-1908 -
It was homesteaded by Anders J. Sjöberg. He came in 1870
and secured the patent Mar. of 1877 - Five children were born
here but only two survived. He came from Dalarna Sweden.
The daughter Anna married Ole Paulson who had the 1/4 section N E 1/4
of this farm. A relative homesteaded the two pieces just north of yours
and passed on to Erik Svedberg. Your land later was owned by
Bill (William) Paulson - a grandson of Anders, son of Ole Paulson.
V.B.A. May. 9-13*

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**

