

#### **SITE INFORMATION**

*SURVEY DATE: Octob	*ADDRESS: _30577 470 <sup>th</sup> Ave.										
*SURVEYOR: _Jim S	*COUNTY:	Clay									
		*CITY:	Y: Beresford								
LOCATION DESCRIPTION: FI	rom Vermillion Sout	h Dakota Highway	50 East	abo	ut 2	mile	es to	Gree	enfield		
Road, turn left, (North) 12-1/2 miles to 306th Street, Turn right (East) 2miles to 470th Ave., turn left (North)											
About ¼ mile on the left (West) side.											
LEGAL DESCRIPTION: SE 1/4,	, 13 – 94 – 51 Garfie	ld Twp.									
*QUARTER 1: SE 1/4		OWNER NAME:	Betty I	tty I. Jensen, 2009Trust							
*QUARTER 2:	OV		309 SE 13 <sup>th</sup> Street								
*TOWNSHIP: Garfield		OWNER CITY: Beresford									
*RANGE: 51		OWNER STATE: South Dakota									
*SECTION: 13		OWNER ZIP: 57004									
ACRES: 159.53		QUAD NAME:									
OWNER CODE 1: P											
OWNER CODE 2:											
OWNER CODE 3:											
HISTORIC SIGNIFICANCE											
*DOE:	REGISTER NAME:										
*DOE DATE:	MULTIPLE PROPERTY NAME:										
REASON INELIGIBLE:											
		•	С	ATE	GOF	RY:					
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L										
DATE LISTED:		SIGNIFICANCE LEVEL 2: N S L									
REFERENCE NUMBER:											
HISTORIC DISTRICT RATING:	C or NC	CRITE	RIA 1:	Α	В	С	D				
PERIOD:		CRITE	RIA 2:	Α	В	С	D				
		CRITE	ERIA 3:	Α	В	С	D				
		CRITE	RIA 4:	Α	В	С	D				
SIGNIFICANCE NOTES:											

#### STRUCTURE DETAILS




SHPO ID:		<u>-</u>							
*PROPERTY NAME:									
OTHER NAME:									
CURRENT FUNCTION:	Storage	FOUNDATION:	Poured concrete foundation						
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	Corri galv. steel roofing over cedar shingles						
HISTORIC FUNCTION:	Dairy barn	ROOF SHAPE:							
HISTORIC SUBFUNCTION:		STRUCTURAL SYSTEM:							
morewice sobi enerion.	Tray and grain storage	-	Gable roof barn						
OCCUPIED:	Yes	TYPE:	-						
ACCESSIBLE:	Yes with permission	WALLS:	vertical siding and corri. galv. steel						
STORIES:	2	SIGNIFICANT PERSON: An	aton Henrikson						
*DATE OF CONSTRUCTION:		LTURAL AFFILIATION:	?						
ALTERED/MOVED NOTES: Original site. Milk cow stanchions have been removed. Roof and walls									
are covered with 26" wide galvanized corrugated steel roofing. Interior has been remodeled into horse									
barn. Two double horse stalls have been added and two pens added on West side.									
INTERIOR NOTES: Has one	row of 3x8 posts with (2	) 2x6's for a beam. 2x8 floor jo	ists. Granary still						
In the NE corner. Tack room in the SE corner, could have been milk room earlier.									
OTHER NOTES: 2x4 stud w	alls, with 2x4 purlins 24"	O.C., 1x8 vertical board siding	and steel						
roofing. Rafters are 2x6's with sheathing and cedar shingles and steel roofing. All dimension lumber									
is rough sawn cottonwood. Two 2x6's brace the top of wall in hayloft down to the floor. These braces									
are 6' - 8' - 6' - 8' - 6' O.C. or	n each side. Windows ar	e 4"x24" four light.							
*PHYSICAL NOTES: Barn is	s good condition.								
*UTM ZONE:		*RESTRICTED: Y o	or N						
*UTM EASTING:									
*UTM NORTHING:									

HAYLOFT

\* = REQUIRED FIELD





FIRST FLOOR





PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: October 30, 2012 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: October 30, 2012 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: October 30, 2012 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: October 30, 2012 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: October 30, 2012

**ROLL NUMBER:** PHOTO NUMBER:

CAMERA DIRECTION: granary in NE corner

First floor, looking NE,



PHOTOGRAPHER: \_

Jim Stone DATE OF PHOTO: October 30, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

First floor, looking NW, post and beam and

CAMERA DIRECTION: horse stall





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: October 30, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking West, 2x6 bracing from top of

CAMERA DIRECTION: wall down to floor.




PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: October 30, 2012

**ROLL NUMBER: PHOTO NUMBER:** 

Hayloft, looking West, Rafters and west gable

CAMERA DIRECTION: end







### **HISTORY**

This farm located in the SE ¼ of Section 13, Garfield Township, Clay County was homesteaded by Ole Johnson.

The 1894, 1901 and 1912 Clay County Atlas lists Anton Hendrickson as the owner.

The 1894, 1901 and 1912 Clay County Atlas lists Anton Hendrickson as the owner.

The 1924, 1937 and 1948 Clay County Atlas lists Anton Henrickson as the owner. I suspect the letter d was dropped in the last name, but could be a different person.

The 1956 Clay County Atlas lists Orville Jensen as the owner.

