

SITE INFORMATION

*SURVEY DATE: July 2	*ADDRESS:	: 45774 314 th Street						
*SURVEYOR: Jim S	*COUNTY:	Clay						
		 *CITY:	Meckling					
LOCATION DESCRIPTION: T	he intersection ofSo	uth Dakota Highwa	ay 50 bi- _l	pass a	nd So	outh l	Dako	ta
Highway 19, West 3-3/4 miles to 458th Ave., turn right (North) about ½ mile to 314th Street, turn left (West)								
about $\frac{1}{4}$ mile on the right (North	h) side.							
LEGAL DESCRIPTION: SE 1/4	25 - 93 - 53 Meckli	ng Twp.						
					_			
*QUARTER 1: SE 1/4			D. A. Olson & Sons LLC					
*QUARTER 2:	·		31729 455 th Street					
*TOWNSHIP: Meckling		OWNER CITY:	 					
*RANGE: <u>53</u>			South Dakota					
*SECTION: <u>25</u>		OWNER ZIP:						
ACRES: 163.16		QUAD NAME:						
OWNER CODE 1: P								
OWNER CODE 2:								
OWNER CODE 3:								
HISTORIC SIGNIFICANCE								
*DOE:	REGISTER NAME:							
*DOE DATE:	MULTIPLE PROPERTY NAME:							
REASON INELIGIBLE:								
			CA	ATEGO	RY:			
NOMINATION STATUS:	SIGNIFICANCE LEVEL 1: N S L							
DATE LISTED:		SIGNII	FICANCE	LEVE	L 2:	N	S	L
REFERENCE NUMBER:								
HISTORIC DISTRICT RATING:	C or NC	CRITE	RIA 1:	А В	С	D		
PERIOD:		CRITE	RIA 2:	A B	С	D		
			ERIA 3:	А В	С	D		
		CRITE	RIA 4:	A B	С	D		
CIONICIO ANOS NOTES								
SIGNIFICANCE NOTES:								


STRUCTURE DETAILS



CUDO ID.									
SHPO ID:		_							
*PROPERTY NAME:									
OTHER NAME:									
CURRENT FUNCTION:	Farm machinery and hay storage	_ FOUNDATION:	Poured concrete Steel roofing						
			over cedar						
CURRENT SUBFUNCTION:	Hay storage	ROOF MATERIAL:							
HISTORIC FUNCTION:	Cattle feeder barn	ROOF SHAPE:	•						
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:							
		STYLE:	Livestock feeder barn						
OCCUPIED:	Yes		Cattle feeder barn						
00001 IED.	Yes with	1112.	2x6, 1x12 vertical						
ACCESSIBLE:	permission	WALLS:	siding, steel						
STORIES:	2	SIGNIFICANT PERSON: S	Steel family						
*DATE OF CONSTRUCTION:	1910 to 1920 CL	ILTURAL AFFILIATION:							
ALTERED/MOVED NOTES:	Original site. Appears	to have a new poured concrete	e foundation and a						
new concrete floor. Walls ar	nd roof have been covere	ed with steel roofing. Doors and	d windows covered						
with steel roofing. Four windows have been replaced aluminum combination windows. Two 12'x8' and									
one 18'x14' overhead doors have been installed on the South wall									
INTERIOR NOTES: Has two	2v6 walls 24' high and 2	'A' hotwoon to support the contr	or of the rafters. The						
INTERIOR NOTES: Has two 2x6 walls 24' high and 24' between to support the center of the rafters. The									
24' high walls have 2x6 studs 4' O.C. 2x8 joists 4' O.C. above the East 13' for a hayloft and 2x8 joists 2' O.C. on the West 13' for a hayloft and grain storage. The 24' high walls have 4' of boards at the bottom									
and are open to the roof, exce									
OTHER NOTES: Windows w	vere 9"x12" four light, tw	o windows close together with	4' to 6' between all						
along on the East and West walls. The exterior walls are 2x6, 4' O.C. with horizontal 2x4 nailers 3' O.C.									
for the 1x12 vertical siding.									
*PHYSICAL NOTES: Barn is	s in good condition. Thi	s barn with the ground to peak	center hayloft and						
The two side haylofts could h	old over 150 tons of loo	se hay.							
This was the Steel Hay Ranch	n. They cut native grass	hay, baled it and had it shipped	l out by the railroad						
from Meckling. They employe	ed many men during the	haying season. The prairie wes	st, north and east of						
Meckling is very heavy blue of	lay and remained native	prairie until larger tractors wer	e able to plow up the						
sod and start farming this are	ea.								
*IITM ZONE:		*RESTRICTED: Y o	r N						
			1.14						
*UTM EASTING: *UTM NORTHING:									




SKETCH MAP





SKETCH MAP



PHOTOGR

* = REQUIRED FIELD





PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: July 23, 2012 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: July 23, 2012 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone **DATE OF PHOTO:** July 23, 2012

ROLL NUMBER: PHOTO NUMBER: CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 23, 2012

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO: July 23, 2012

Jim Stone

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North, 2x6wall x 24' high, supports rafters, East

CAMERA DIRECTION: side



PHOTOGRAPHER: Jim Stone

DATE OF PHOTO: July 23, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, 2x6 wall 24' high supporting rafters,

CAMERA DIRECTION: West side





PHOTOGRAPHER: DATE OF PHOTO: Jim Stone

July 23, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North, wall bracing to the CAMERA DIRECTION: hayloft floor, West side



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 23, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking North grain chutes from the

CAMERA DIRECTION: hayloft.






PHOTOGRAPHER: __ DATE OF PHOTO:

Jim Stone July 23, 2012 ROLL NUMBER: PHOTO NUMBER:

Hayloft, West side, looking North, hay or grain storage and wall

CAMERA DIRECTION: bracing





CLAY CO., SD

© Farm & Home Publishers. Ltd.



HISTORY

This farm located in the SE ¼ of Section 25, Meckling Township, Clay County was homesteaded by Joseph Hayes.

The 1894 Clay County Atlas lists H. Robinson as the owner.

The 1901 Clay County Atlas lists William E. Doyle as the owner.

The 1912 Clay County Atlas lists Thomas J. Steele as the owner.

The 1924 and 1937 Clay County Atlas lists Ella Steele as the owner. The 1937 lists Martin Knutson as the operator (renter).

The 1948 and 1956 Clay County Atlas lists J. A. Doyle as the owner.

