


SITE INFORMATION

*SURVEY DATE: July 9 *SURVEYOR: Jim S	•	*ADDRESS: *COUNTY:	: 31704 Bergen Ave. : Clay								
		*CITY:	*CITY: Meckling								
LOCATION DESCRIPTION: From Vermillion South Dakota Highway 50, West about 1mile to South Dakota Highway 19 South, turn left about 300' to Timber Road, turn right (West) about 5-3/4 miles to											
Bergen Ave., turn right (North) about ¼ mile, on right (East) side.											
LEGAL DESCRIPTION: Lot J of NW ¼, NE ¼, 15 – 92 – 53 Norway Twp.											
*QUARTER 1: NE 1/4		OWNER NAME:			Glen J. & Denice A. Gilbertson						
*QUARTER 2:	OWN	IER ADDRESS:	31704 Bergen Ave.								
*TOWNSHIP: Norway		OWNER CITY:	Meckling								
*RANGE:53		WNER STATE:	South Dakota								
*SECTION: 15		OWNER ZIP:	57069								
ACRES: <u>3.8</u>		QUAD NAME:									
OWNER CODE 1: P											
OWNER CODE 2: F S L	Р										
OWNER CODE 3: F S L	Р										
—— HISTORIC SIGNIFICANCE											
*DOE:		DECISTED NAME.									
*DOE DATE:		REGISTER NAME: MULTIPLE PROPERTY NAME:									
REASON INELIGIBLE: MULTIPLE PROPERTY NAME:											
NEAGON INCLIGIBEE:											
			CAT	EGOF	RY:						
NOMINATION STATUS:		SIGNIFICANCE LEVEL 1: N S L									
DATE LISTED:		SIGNIFICANCE LEVEL 2: N S L			L						
REFERENCE NUMBER:											
HISTORIC DISTRICT RATING:	C or NC	CRITE	RIA 1: A	В	С	D					
PERIOD:		CRITE	RIA 2: A	В	С	D					
		CRITE	RIA 3: A	В	С	D					
		CRITE	RIA 4: A	В	С	D					
SIGNIFICANCE NOTES:											



STRUCTURE DETAILS								
SHPO ID:								
*PROPERTY NAME:		_						
OTHER NAME:								
0111 <u>21</u> 111111121								
	Farm machinery							
CURRENT FUNCTION:	storage	FOUNDATION:	Poured concrete					
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	Steel over cedar shingles					
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable					
HISTORIC SUBFUNCTION:	Hay storage		Balloon framing					
HISTORIC SUBFUNCTION.	nay storage		Gable roof barn					
OCCUPIED.	Vac		-					
OCCUPIED:	Yes	TYPE:	Livestock barn 2x6, sheathing					
			&1/2"x6" cedar lap					
	Yes with		siding & steel					
ACCESSIBLE:	permission	WALLS:	roofing					
STORIES:	2	SIGNIFICANT PERSON:	Elling Myron					
*DATE OF CONSTRUCTION:	About 1920 C	CULTURAL AFFILIATION:	Norwegian					
ALTERED/MOVED NOTES: _	Original site. Roof a	nd walls have been covered with	steel roofing.					
All stalls, stanchions and posts and beams have been removed. The barn has been converted into a								
swine farrowing barn. Additions have been added to the West and the North sides much later than the								
original barn. Interior walls a	nd ceiling are insulated	d and lined. I could not access th	ne hayloft.					
INTERIOR NOTES: Do mot le		d b a man a command b and after	floor loistoons					
INTERIOR NOTES: Do not know what the posts and beams were to support hayloft floor. Joists are 2x8. All of the 2x6's for studs, rafters and bracing, 2x8 floor joists and sheathing are rough sawn								
	s, ratters and bracing, 2	ex8 floor joists and sheathing are	rougn sawn					
cottonwood.	411.6411.6							
OTHER NOTES: Windows were 4"x24" four light. 2x6 stud walls with diagonal sheathing and ½"x6"								
		barn inside the North original lea						
		to are 2x4, with 2x4 rafters and 2						
are all rough sawn cottonwood immigrant.	od. Barn was built by I	Nels Peterson a carpenter by trac	de and a Swedish					
	s in good condition.							
	o in good containoin							









PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: July 9, 2012 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 9, 2012 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 9, 2012 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: July 9, 2012 PHOTO NUMBER: 4

CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 9, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking West into lean-to, 2x4 wall and

CAMERA DIRECTION: diagonal sheathing




PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone July 9, 2012

ROLL NUMBER: PHOTO NUMBER:

First floor, looking West into lean-to, diagonal sheathing on North wall CAMERA DIRECTION: of barn and 1x8 shiplap





PHOTOGRAPHER: ? ROLL NUMBER: DATE OF PHOTO: ? PHOTO NUMBER: 7

CAMERA DIRECTION: Original barn years ago.




PHOTOGRAPHER: ? ROLL NUMBER: _____ PHOTO NUMBER: _____ PHOTO NUMBER:

Original barn many years ago, might be when it

CAMERA DIRECTION: was new.





arm: & Home Publishers. I trl.

29

CLAY CO., SD



HISTORY

This farm, located in the NW ¼ of the NE ¼, Section 15, Norway Township, Clay County was homesteaded by Elling Olson.

The 1894 Clay County Atlas lists S. S. Myron as the owner.

The 1901 Clay County Atlas lists Elling M. Myron as the owner.

The 1912 Clay County Atlas lists J. G. Iverson as the owner.

The 1924 Clay County Atlas lists Elling M. Myron as the owner.

The 1937 Clay County Atlas lists E. & J. Iverson as the owners.

The 1948 Clay County Atlas lists Arthur Iverson as the owners.

The 1956 Clay County Atlas lists D. E. Myron as the owners.

The Following Information Is Furnished by

Milo Gilbertson

Elling Myron lived on this farm at the time the barn was built. Milo Gilbertson bought this farm from Don Myron, a son of Elling Myron. Milo and Sally Gilbertson lived here for most of their life. They farmed and raised a lot of hogs.

Milo said that a Nels Peterson immigrated from Sweden in 1914. He was a carpenter and built kitchen cabinets for Elling Myron in 1917 in the house that still stands today. Glen Gilbertson the son of Milo and Sally Gilbertson bought the farmstead and lives in the house.

Nels Peterson is believed to have built the barn about 1920. He built other barns and did carpentry work in the area. He just disappeared from the area. He died in 1943 and had requested to be buried at the Norwegian Cemetery. This would be the Meckling Cemetery.

Nels Peterson was married in Sweden, but did not bring his family to America. He was going to make his fortune and then send for his family. His wife finally divorced Nels, but stayed in Sweden. Milo did not know why he did not send for his family after he established his life in America.

