SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE

HISTORIC SITES SURVEY STRUCTURE FORM

SITE INFORMATION

***SURVEY DATE:**	October 28, 2012	***ADDRESS:**	4235 East Main Street
***SURVEYOR:**	Jim Stone	***COUNTY:**	Clay
		***CITY:**	Vermillion

LOCATION DESCRIPTION: Main Street in Vermillion, East from Crawford Road about 2miles, just past Fairview Ave. continue on the gravel East about ¼ mile, on the right (South) side.

LEGAL DESCRIPTION: Cusick Addn. In NW ¼, NW ¼, 22 – 92 – 51 Fairview Twp.

***QUARTER 1:**	NW 1/4	**OWNER NAME:**	Mike Roche
***QUARTER 2:**		**OWNER ADDRESS:**	4235 East Main Street
***TOWNSHIP:**	Fairview	**OWNER CITY:**	Vermillion
***RANGE:**	51	**OWNER STATE:**	South Dakota
***SECTION:**	22	**OWNER ZIP:**	57069
ACRES:	15.9	**QUAD NAME:**	
OWNER CODE 1:	P		
OWNER CODE 2:			
OWNER CODE 3:			

HISTORIC SIGNIFICANCE

***DOE:**		**REGISTER NAME:**
***DOE DATE:**		**MULTIPLE PROPERTY NAME:**
REASON INELIGIBLE:		

CATEGORY: _____

NOMINATION STATUS:	**SIGNIFICANCE LEVEL 1:**	N S L
DATE LISTED:	**SIGNIFICANCE LEVEL 2:**	N S L
REFERENCE NUMBER:		
HISTORIC DISTRICT RATING: C or NC	**CRITERIA 1:**	A B C D
PERIOD:	**CRITERIA 2:**	A B C D
	CRITERIA 3:	A B C D
	CRITERIA 4:	A B C D

SIGNIFICANCE NOTES:

STRUCTURE DETAILS

* = REQUIRED FIELD

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE

HISTORIC SITES SURVEY STRUCTURE FORM

SHPO ID:

*PROPERTY NAME:

OTHER NAME:

CURRENT FUNCTION:	Storage	**FOUNDATION:**	Poured concrete foundation
CURRENT SUBFUNCTION:	Storage	**ROOF MATERIAL:**	Asphalt shingles over cedar shingles
HISTORIC FUNCTION:	Livestock barn	**ROOF SHAPE:**	Gothic round
HISTORIC SUBFUNCTION:	Hay and grain storage	**STRUCTURAL SYSTEM:**	Balloon framing
		STYLE:	Gothic round roof barn
OCCUPIED:	Yes	**TYPE:**	Livestock barn
ACCESSIBLE:	Yes with permission	**WALLS:**	2x6 stud, sheathing and ½"x6" cedar lap siding
STORIES:	2	**SIGNIFICANT PERSON:**	Carrie L. Burgess
*DATE OF CONSTRUCTION:	1920 to 1930	**CULTURAL AFFILIATION:**	?

ALTERED/MOVED NOTES: Original site. Milk cow stanchions and horse stalls have been removed. Asphalt shingles applied over cedar shingles. Bottom 4' of 6"cedar lap siding has been replaced with 1x6 car siding.

INTERIOR NOTES: Has two rows of 6x6 posts with 6x10 for beams. 2x10 floor joists. Granary and feed room and stairs are still in place. Granary still in hayloft. All 2x6's, 2x10's, 6x6's, and 6 x10's are rough sawn cottonwood. Cottonwood lumber most likely came from saw mill on Wallace Cusick's farm by Burbank. Wallace Cusick was father of Harold Cusick.

OTHER NOTES: 2x6 stud walls with 1x8 sheathing and ½"x6" cedar lap siding. Rafters are six plies of ¾"x 1-1/2" cedar. Rafters are manufactured and each rafter has a stamp M. Slagle Co. Elk Point, So. Dak. 1x10 sheathing on roof. Asphalt shingles over cedar shingles. 8"x10" four light windows on first floor. Has two 8"x10" six light windows in West wall of hayloft.

*PHYSICAL NOTES: Barn is in good condition.

*UTM ZONE:

*UTM EASTING:

*UTM NORTHING:

*RESTRICTED: Y   or   N

SKETCH MAP

6'x10'6 GRANARY

FEED ROOM

STAIRS

2°

CHUTE FROM GRANARY IN HAYLOFT

32'

9'

10'6

11'

10'6

10'

8'-6

11'-6

12'

3°

42'

FIRST FLOOR

3/4"×1-½" 6 PLY CEDAR RAFTERS

1×10 SHEATHING

21'

2'6

10'-6 × 12' GRANARY IN HAYLOFT

2×10 JOISTS

7'6

6×10 BEAM 6×6 POSTS

2×6 WALLS
1×10 SHEATHING
1½"×6" CEDAR LAP SIDING

CONC. PIERS

12" CONC. FOUNDATION

PHOTOGR

N

8

7

6

HAYLOFT

4

3

5

1

2

FIRST FLOOR

* = REQUIRED FIELD

SOUTH DAKOTA STATE HISTORICAL SOCIETY
Department of Tourism and State Development

PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	October 28, 2012	PHOTO NUMBER:	1
		CAMERA DIRECTION:	Looking NE, SW corner

PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	October 28, 2012	PHOTO NUMBER:	2
		CAMERA DIRECTION:	Looking NW, SE corner

* = REQUIRED FIELD

SOUTH
DAKOTA STATE
HISTORICAL SOCIETY
Department of Tourism and State Development

PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	October 28, 2012	PHOTO NUMBER:	3
		CAMERA DIRECTION:	Looking SW, NE corner

PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	October 28, 2012	PHOTO NUMBER:	4
		CAMERA DIRECTION:	Looking SE, NW corner

* = REQUIRED FIELD

PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	October 28, 2012	PHOTO NUMBER:	**5**

CAMERA DIRECTION: **First floor, looking NW, posts, 6x10 beam, granary and stairs in the NW corner**

PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	October 28, 2012	PHOTO NUMBER:	**6**

CAMERA DIRECTION: **Hayloft, looking East, ¾"x 1-1/2" six ply cedar manufactured rafters**

* = REQUIRED FIELD

6

SOUTH
DAKOTA STATE
HISTORICAL SOCIETY
Department of Tourism and State Development

PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	October 28, 2012	PHOTO NUMBER:	7
		CAMERA DIRECTION:	Hayloft, looking East, Gable end

| PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	October 28, 2012	PHOTO NUMBER:	8
		CAMERA DIRECTION:	Hayloft, looking NW, Granary in NW corner, above granary below

* = REQUIRED FIELD

SOUTH
DAKOTA STATE
HISTORICAL SOCIETY
Department of Tourism and State Development

T-91-92-N   FAIRVIEW DIRECTORY   R-51-W

(Residents - Owners or Renters)

FAIRVIEW TOWNSHIP

SECTION 15

1 Turnbaugh, V 5009
2 Ashes, Severn 5225
3 Behrmann, David 31761
4 Albers, Dave 4745
5 Ouellette, Loren 31765

6 Meyer, Leroy 4206
7 Nauertz, James 4306
8 Schoenrock, K 4424
9 Knutson, Richard 5101
10 Mogck, John 4733
11 Miller, Stan 4901
12 Hovden, Donald 4905

SECTION 20

1 2509
2 Crew, M 2531
3 Neitzke, Mark 2703
4 Cook, Cleland 2711
5 Miskimins, Robin 2835
6 Ahmed, Mike 2925

© Farm & Home Publishers, Ltd.   19   CLAY CO., SD

HISTORY

This farm located in the NW ¼ of the NW ¼ in Section 22, Fairview Township, Clay County was homesteaded by Timothy K. Hovey.

The 1894, 1901, 1912 and 1924 Clay County Atlas lists Carrie L. Burgess as the owner. Carrie L. Burgess most likely built or had this barn built as the construction is from about that period of time.

The 1937 Clay County Atlas lists Carrie L Burgess Estate as the owner and P. Ouellette as the operator (renter).

The 1948 Clay County Atlas lists Wallace L. Cusick as the owner.

The 1956 Clay County Atlas lists Harold Cusick as the owner.