SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE

HISTORIC SITES SURVEY STRUCTURE FORM

SITE INFORMATION

***SURVEY DATE:** Aug. 18, 2012   ***ADDRESS:** 31738 460th Ave.

*SURVEYOR: Jim Stone   ***COUNTY:** Clay

*CITY: Vermillion

LOCATION DESCRIPTION: From Vermillion west on South Dakota Highway 50 about 1 mile to South Dakota Highway 19, turn left (South) about 300' to Timber Road, turn right (West) about 1-3/4 miles to 460th Ave., turn right (North) about 1/8th mile, on the right (East) side.

LEGAL DESCRIPTION: Lot 3, re-plat of Parcel A in Gov't Lot 1, 16 – 92– 52 Vermillion Twp.

*QUARTER 1: NW 1/4   **OWNER NAME:** Michelle L. Romsdahl

*QUARTER 2:   **OWNER ADDRESS:** 31738 460th Ave.

*TOWNSHIP: Vermillion   **OWNER CITY:** Vermillion

*RANGE: 52   **OWNER STATE:** South Dakota

*SECTION: 16   **OWNER ZIP:** 57069

ACRES: 2.0   **QUAD NAME:**

OWNER CODE 1: P

OWNER CODE 2:

OWNER CODE 3:

HISTORIC SIGNIFICANCE

*DOE: **REGISTER NAME:**

*DOE DATE: **MULTIPLE PROPERTY NAME:**

REASON INELIGIBLE:

CATEGORY:

NOMINATION STATUS: **SIGNIFICANCE LEVEL 1:** N   S   L

DATE LISTED: **SIGNIFICANCE LEVEL 2:** N   S   L

REFERENCE NUMBER:

HISTORIC DISTRICT RATING: C   or   NC   **CRITERIA 1:** A   B   C   D

PERIOD: **CRITERIA 2:** A   B   C   D

CRITERIA 3: A   B   C   D

CRITERIA 4: A   B   C   D

SIGNIFICANCE NOTES:

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM

SOUTH
DAKOTA STATE
HISTORICAL SOCIETY
Department of Tourism and State Development

STRUCTURE DETAILS

SHPO ID:

*PROPERTY NAME:

OTHER NAME:

CURRENT FUNCTION:	Vacant	**FOUNDATION:**	Poured concrete
CURRENT SUBFUNCTION:	Storage	**ROOF MATERIAL:**	Steel over cedar shingles
HISTORIC FUNCTION:	Livestock barn	**ROOF SHAPE:**	Gambrel
HISTORIC SUBFUNCTION:	Hay storage	**STRUCTURAL SYSTEM:**	Balloon framing
		STYLE:	Gambrel roof barn
OCCUPIED:	Yes	**TYPE:**	Livestock barn
ACCESSIBLE:	Yes with permission	**WALLS:**	2x6, 1x6 #106 drop siding
STORIES:	2	**SIGNIFICANT PERSON:**	Iver (Iverson) Hanson
*DATE OF CONSTRUCTION:	Early 1900's	**CULTURAL AFFILIATION:**	Norwegian

ALTERED/MOVED NOTES: Original site. All horse stalls and milk cow stanchions have been removed. Roof covered with steel roofing over cedar shingles. Center 1/3 of hayloft floor removed and about 8' has been rebuilt on North and south sides, leaving a hole about 7' x 12' in the center of the hayloft floor.

INTERIOR NOTES: Has two rows 4x6 posts and a 2x8 rough sawn cottonwood for a beam. 2x6 floor joists. All evidence of any stalls or stanchions is gone.

OTHER NOTES: No windows. Walls are 2x6 with 1x6 #106 drop siding. Rafters are 2x4. Two 3x6 rough sawn cottonwood posts with a 4x4 beam on each side in hayloft to support the hip. 8' wide sliding doors in the center of the North and South walls. No walk doors.

*PHYSICAL NOTES: Barn is in fair condition. The roof is not leaking. Needs new siding.

*UTM ZONE: ***RESTRICTED: Y   or   N**

*UTM EASTING:

*UTM NORTHING:

SKETCH MAP

2x4 RAFTERS
4x4 BEAM
2x6 BRACE
4x6 POST
12'
16'
2'
6'
2x6 JOISTS
4x6 POSTS
2x8 BEAM
8'
10'-6"

2x6 WALL
1x6 #106 DROP
SIDING

8'
24'
9'-8"
9'-8"
12'-8"
8'-9"
10"
8'-9"
8'
32'

FIRST FLOOR

③

N

⑦

PHOTOGR

⑥

HAYLOFT

* = REQUIRED FIELD

⑤

④

FIRST FLOOR

①

②

SOUTH
DAKOTA STATE
HISTORICAL SOCIETY
Department of Tourism and State Development

PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	Aug. 18, 2012	PHOTO NUMBER:	1
		CAMERA DIRECTION:	Looking NE, SW corner

PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	Aug. 18, 2012	PHOTO NUMBER:	2
		CAMERA DIRECTION:	Looking NW, SE corner

* = REQUIRED FIELD

SOUTH
DAKOTA STATE
HISTORICAL SOCIETY
Department of Tourism and State Development

PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	Aug. 18, 2012	PHOTO NUMBER:	3
		CAMERA DIRECTION:	Looking SE, NW corner

PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:	
DATE OF PHOTO:	Aug. 18, 2012	PHOTO NUMBER:	4
		CAMERA DIRECTION:	First floor, looking NE, post and beam

* = REQUIRED FIELD

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE

HISTORIC SITES SURVEY STRUCTURE FORM

SOUTH
DAKOTA STATE
HISTORICAL SOCIETY
Department of Tourism and State Development

PHOTOGRAPHER:	Jim Stone	**ROLL NUMBER:**	
DATE OF PHOTO:	Aug. 18, 2012	**PHOTO NUMBER:**	**5**
		CAMERA DIRECTION:	**First floor, looking SW, post, and 2x8 rough sawn cottonwood beam**

PHOTOGRAPHER:	Jim Stone	**ROLL NUMBER:**	
DATE OF PHOTO:	Aug. 18, 2012	**PHOTO NUMBER:**	**6**
		CAMERA DIRECTION:	**Hayloft, looking East, 4x6 post and 4x4 beam supporting hip**

* = REQUIRED FIELD

SOUTH DAKOTA STATE HISTORICAL SOCIETY
Department of Tourism and State Development

PHOTOGRAPHER:	Jim Stone	**ROLL NUMBER:**	
DATE OF PHOTO:	Aug. 18, 2012	**PHOTO NUMBER:**	7
		CAMERA DIRECTION:	Hayloft, looking East, 4x6 post, 4x4 beam and bracing

* = REQUIRED FIELD

SOUTH
DAKOTA STATE
HISTORICAL SOCIETY
Department of Tourism and State Development

T-91-92-N   VERMILLION DIRECTORY   R-51-52-W
(Residents - Owners or Renters)

SPIRIT MOUND TWP.   PRAIRIE CENTER TWP.

VERMILLION TOWNSHIP

SECTION 2N
1. Koster, John 31550
2. Patri, V 31554
3. Sommervold, Gerald 31558

SECTION 7
1. Johnson, Allen 2111
2. Wheelock, Randy 2017
3. Zimmerman, J 504
4. 1909
5. Laitala, Terry 711
6. Olson, Eric 1817
7. Simons, Kai 1421

SECTION 11
1. Gilbertson, Marty 2021
2. Storm, John 2109
3. Campbell, B 1919
4. McBride, Richard 2102

5. Heisinger, James 2118
6. Templeman, J 915
7. Brown, Ralph 937
8. Bock, Robert 1017
9. Wingen, Pat 1103
10. Robinson, Curt 1121
11. Ford, Steve 912

SECTION 12
1. Mock, M 2411
2. Pasqualucci, J 2507
3. Swallow, John 2523

SECTION 16
1. 46002
2. Kober, Tom 46004
3. Myron, Warren 46008
4. Johnson, Robert L 46020
5. Halverson, Ernest 46044
6. Struckman, Dave 46048

DIXON CO., NE

© Farm & Home Publishers, Ltd.   41   CLAY CO., SI

HISTORY

Section 16 was a School Section and could not be homesteaded. Any rent or sales of any part of this Section went to a county fund for rural schools.

The 1894 Clay County Atlas lists Ole Thompte as the owner.

The 1901, 1912 and 1924 Clay County Atlas lists Julia Hanson as the owner.

The 1937 Clay County Atlas lists Mrs. Anna Hanson as the owner and M. R. Hanson as the operator (renter).

The 1948 Clay County Atlas lists Anna Hanson as the owner.

The 1956 Clay County Atlas lists M. K. Hanson as the owner.

The Following Information was furnished by
Carol (Greg) Tramp

Iver Iverson immigrated from Homre, Norway. He was born Oct. 22, 1860 in Norway. He had two brothers who had immigrated earlier and changed their last name to Hanson, so Iver changed his last name to Hanson.

He married Anne Larson from Quandahl, Iowa. She was born July 2, 1866 and died October 23, 1947.

Their children were Albert Hanson, Martin Hanson, Sarah (Hanson) Gray, Ludwig Hanson, and Henry Hanson.

Ludwig (Lud) Hanson was born December 19, 1905, in Norway Township, Vermillion, South Dakota. He died October 7, 1978, in Yankton South Dakota. He is buried in the Meckling Cemetery.

Ludwig married Andrea C. (?) Hanson, April 19, 1937 at Julesberg, Colorado. She was born June 19, 1898 in Norway Township, Vermillion, South Dakota. She died February 23, 1972 in Norway Township, Vermillion, South Dakota. She is buried in the Meckling Cemetery.

Lud and Andrea lived on this farm. It was owned by Anne Larson, Lud's mother. Lud and Andrea bought the farm from Anne Larson's estate after she died.

Iver (Iverson) Hanson would have built this barn or had it built.