

SITE INFORMATION

*SURVEY DATE: January 8, 2013

*ADDRESS: 46913 303rd Street

*SURVEYOR: Jim Stone

*COUNTY: Clay *CITY: Beresford

LOCATION DESCRIPTION: From Vermillion, South Dakota Highway 50, East 2 miles to Greenfield Road, Turn left (North) 15-1/4 miles, on left (West) side

LEGAL DESCRIPTION: Bylander Tracts 1 & 2, SE ¹/₄, NE 1/4, 3 – 94 – 51 Garfield Twp.

*QUARTER 1:	NE 1/4		-	OWNER NAM									
*QUARTER 2:			OV	VNER ADDRES	SS: <u>30</u>)337	Gre	enfie	ld R	oad			
*TOWNSHIP:	Garfield		_	OWNER CI									
*RANGE:	51		_	OWNER STAT	TE: <u>So</u>	outh	Dak	ota					
*SECTION:	3		_	OWNER Z	2IP: <u>57</u>	'004							
ACRES:	5.84		_										
OWNER CODE 1:	Р												
OWNER CODE 2:													
OWNER CODE 3:													
HISTORIC SIGN	FICANCE												
*D0	DE:			REGISTER	R NAME								
							Y N/	AME:					
*DOE DATE: REASON INELIGIBLE:				-									
				-		С	ATE	GOF	RY:				
NOMINATIO	N STATUS:			SI	GNIFIC							L	
					GNIFIC	ANC	ELE	EVEL	. 2:	Ν	S	L	
HISTORIC DISTRIC				_	RITERIA	A 1:	Α	в	С	D			
	-			_					-				
				-	RITERIA				-				
				0.		• ••	~	2	Ŭ	2			
SIGNIFICANCE NOT	res:												
STRUCTURE DE	TAILS												



SHPO ID:	CL00300009			
*PROPERTY NAME:	Daniel A. Messler He	omestead		
OTHER NAME:				
CURRENT FUNCTION:	Shop	FOUNDA	TION:	Native rock, no mortar
CURRENT SUBFUNCTION:	Storage	ROOF MATE	RIAL:	Asphalt shingles over cedar shingles
HISTORIC FUNCTION:	Livestock barn	ROOF SH	IAPE:	Gable
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYS	STEM:	Balloon framing
		Sī	TYLE:	Gable roof Swedish barn
OCCUPIED:	Yes	1	TYPE:	Livestock barn
ACCESSIBLE:	Yes with permission	WALLS:		2x4 R.S. with 1x6 #106 drop siding
STORIES:	2	SIGNIFICANT PERSON:	Danie	el A. Messler
*DATE OF CONSTRUCTION:	Pre 1880	CULTURAL AFFILIATION:		Swedish

ALTERED/MOVED NOTES: Original site. Any evidence of milk cow stanchions or stalls has been re-moved. 9'-6"x26' lean-to added on the North side at a later date. Several 2x4 posts have been added in the hayloft to support sagging rafters. Also 2x6 horizontal braces have been added in the hayloft to keep the East and West walls from spreading apart.

INTERIOR NOTES: <u>Has two rows of 6x6 posts, with 4x6's for a beam in the South half of the barn.</u> Has two rows of row of 4" round posts and (2) 2x6's for a beam in the North half of the barn. There is a 2x4 stud wall with 1x8 shiplap, between the North and South sides of the barn. Floor joists are 2x6's. OTHER NOTES: <u>2x4 stud walls with 1x6 #106 drop siding</u>. Rafters are 2x4's. Nine single and one double horse stalls are still in place in the South half of the barn. A 5' x 8' granary is still in place in the SE corner of the hayloft. There is a tack room and feed room in the SE corner on the first floor directly below, the granary above. Windows are 8"x10" four light. All of the 2x4's and 2x6's and material in the horse stalls are rough sawn cottonwood. Foundation is large native stones with smaller stones fit between and no mortar.


	Barn is in fair condition. Needs straightening. Some of the doors need re-built.
*PHYSICAL NOTES:	Some siding needs replacing.


*UTM ZONE:	*RESTRICTED:	Y	or	Ν
*UTM EASTING:				
*UTM NORTHING:				



Х 2.44 R.S. A A FTARS 9 ,1 Ņ 2 * 6 R 5 101575 1 0 SOUTH ELEVATION 2×4 R.S, STUDS 1×6 #106 DR6P 5101NG

SKETCH MAP



















 PHOTOGRAPHER:
 Jim Stone
 ROLL NUMBER:

 DATE OF PHOTO:
 January 8, 2013
 PHOTO NUMBER:

PHOTO NUMBER: 5 First floor, North lean-to, looking West, Hay feed CAMERA DIRECTION: rack and feed bunk.







PHOTOGRAPHER: _____ DATE OF PHOTO: _____ Jim Stone January 8, 2013 ROLL NUMBER: PHOTO NUMBER:

7

First floor, looking North, horse stalls on the West wall in South half of

CAMERA DIRECTION: barn.



PHOTOGRAPHER: _ DATE OF PHOTO: _ Jim Stone January 8, 2013 ROLL NUMBER: ______



First floor, looking SE, single horse stalls on East side in the South CAMERA DIRECTION: half of barn.

* = REQUIRED FIELD

Jim Stone

January 8, 2013






PHOTOGRAPHER: _____ DATE OF PHOTO: ROLL NUMBER: PHOTO NUMBER:

9

First floor, looking North, two pens, any evidence of what the North area CAMERA DIRECTION: was used for is gone.




January 8, 2013





PHOTOGRAPHER: _____ DATE OF PHOTO: _____ ROLL NUMBER: PHOTO NUMBER:

PHOTO NUMBER: 11 Hayloft, looking North, 2x4 posts and 2x6 CAMERA DIRECTION: horizontal bracing.





64th A	94-N ve	UNIVERSIT	YAVE	466th AVE	RFIEL	dents - Owners	OD TWP.	GREENFIELD	DIRD	469th A			10th AVE
303rd	artes om 346 6	UNIVERSITY AVE	5 Gordon R Johnson 30372	466th AVE	Christopher Kinner 44629 4 Vick	467th AVE	Carlson 30332 3 Terry Jensen Gary 46718 Carlson #46730	K 30337 ■	Clark 30362	469th AVE	#46913 St	Leon Hanse 4697 1	470th
30401	C . The 464	dorff 69 Todd III johnson 30437 J Berg II 30451	07iand Sternguist ■ 30472 Det 07 46504 30 St.	nnis conneli 485 •	Mèrie Artistensen 30404 9		Alden Lundquist 46733 10		11 Jewdale St	M Schurch 30433 •	= 30438 Ave Kendal Frick 30474) 12	Keith Kirkebak 30415
305th	st 18 	Ryan Bear 30535	•K Hansen 30512 17 HUB CITY	hinson	Dean Lindstrom 30524 16 Duane 46638 B	Rolf Olson 46664	Roland Cyfe 30534 15		Randall Jensen 30540 12 I Taylor 46820	ason Jensen 46886	Charles Jensen 30514	13	Ron Larsen 30535
306# #D	ngstrom 6224 19		44507 53 54 77 10 77 10 77 10 70 70 70 70 70 70 70 70 70 70 70 70 70	Craig Nelson 30641	21	46677 St	M Hamérsma 46741 22 46751 51 =	Brian	23 Kend Swee ∎4683	al	46904 ∎St	24 Je =4	oger ensen 6958
jerry Whe 4644 L Han 464	sen	Scott Mollman 30717 HILL ST	and the second se	<u> </u>	Mike Zwier 30724 ames Danielson 10750 28 Marvin Christensen 30766		s 27 Hein = 30768		30716 Rd Sd Sd Sd Sd Sd Sd Sd Sd Sd Sd Sd Sd Sd	M Saur 46878 Arlin Hassen Hassen	Er Al •40	25 ic iexander \$926	
	08th ST			Craig Jensen 30835 = J Ballinger 30839	33 David Alexander 30872	Larry Larson 30869 =	Curtis Fickbohm 30836	4 30879 Rd ■	Don Reid Jensen Reid Jensen Jense 46825 A682 3		■L Lamie 30834	36 David Howan	Bryce Jensen 30845 ■

PRAIRIE CENTER TWP.

© Farm & Home Publishers, Ltd.



HISTORY

This farm located in the NE ¹/₄ of Section 3, Garfield Township, Clay County was homesteaded by Daniel Anders Musler. He changed his last name to be more Americanized.

The 1901, 1912 and 1924 Clay County Atlas lists Daniel A. Messler as the owner. Spelling of last name was changed.

The 1937 Clay County Atlas lists Annie and Minnie Bylander as the owners.

The 1948 and 1956 Clay County Atlas lists Minnie Bylander as the owner.

The following is from the

Beresford Centennial Book 1884 – 1984

The Messler-Bylander homestead, located on NE ¹/₄, Section 3, in Garfield Township, Clay County was filed upon as a homestead in 1869 by Daniel Messler. Daniel was born in 1844 in Svardsjo Parish, the province of Dalarna, Sweden. He came to the United States with his brother, Erick in 1868 to the State of Illinois. While there, the brothers changed their name from Andersson to Messler. Daniel came to Dakota Territory in 1869 and filed his land claim that year, receiving patent to the land in 1876. He made application for U.S. citizenship in 1869. In the early years, Daniel worked with his brother Erik, on the railroad at Plattsmouth, Nebr., except for the number of days required in residence on the claim. On the claim, he had a dug for a home.

Daniel was married in 1884 to Anna Jansson, who was born in 1851 at Fellingsbro Parish, Narke, Orebro Lan, Sweden. She came to New York in 1882 and worked there before coming to live with a half–brother in Clay County. They lived on the homestead until they retired to Vermillion in 1919. Daniel died after a fall in 1924 and Anna returned to live on the farm until her death in 1937.

Two daughters, Anna, born in 1885 and died in 1889 and Ida (Minnie), were born to the Messlers. Minnie was schooled at the original early Newdale School and the building fallowed. As a child, she remembered hiding beneath a bed when Indians crossed th a spring across the section. She also remembers riding a bicycle or driving a buggy to get the mail once a week at the Alsen Post Office before there was rural mail delivery by horse from Beresford.



John Bylander was born in 1883 in Ore Parish, Vastergotland, Sweden. He left his rocky rural home at the age of 13 to work in a bicycle factory in Gothenburg, Sweden and immigrated at the age of 16 to the U. S. coming to Chicago in 1900. He became a citzen in 1902 at Denver, Colorado. In 1912 John married Minnie Messler.

The bylanders first lived at Omaha where a son Daniel was born in 1916. They came to the Clay County farm in 1919 when the Messlers retired to Vermillion. Their second son, John was born at the farm in 1919. Both sons attended Newdale School. Daniel Bylander farmed the homestead until his death in 1939. Minnie Bylander continued to live on the farm until she died on 1981 at the age of 92 years.

John was married in 1946 to Elizabeth Howell, Tampa, Florida. After his wartime service with the USAF in the Pacific he was killed in 1949. They had one son John, born in 1948 who now lives a Cleveland, Ohio with his wife and three children. Daniel lived on the farm and actively farmed it from 1939 till retirement on the farm in 1981. He was married in 1949 to L'Nora Bowden, born at Hooker, in 1919 to English and Danish parents.

They have five children all of whom attended for eight years the same Newdale School as their father and grandmother. The five children are; Karin, Des Plaines, Illinois; D. Martin, Austin, Texas; Ruth, San Antonio, Texas; Nancy, Huston, Texas; and Thomas of Columbus, Ohio.

Three generations have lived on the farm since it was homesteaded and in the present house built in 1901. This house is the third residence after the original dugout used for "proving up" the claim.