

SITE INFORMATION

*SURVEY DATE: November 27, 2012

ADDRESS: <u>46470 303rd Street</u> *COUNTY: Clay

*SURVEYOR: Jim Stone

*CITY: Centerville

LOCATION DESCRIPTION: From the intersection of South Dakota Highway 50 bi-pass and University Ave., North 15 miles to 303rd Street, turn left (West) about ¹/₄ mile on the right (North) side

LEGAL DESCRIPTION: Norin Tract 1, SE ¹/₄, 31 – 95 – 51 Glenwood Twp.

*QUARTER 1:	SE 1/4	OWNER NAME:	Patrica A. Nori	n				
*QUARTER 2:		OWNER ADDRESS:	46470 303 rd St	reet				
*TOWNSHIP:	Glenwood	OWNER CITY:	Centerville					
*RANGE:	51	OWNER STATE:	South Dakota					
*SECTION:	31	OWNER ZIP:	57014					
ACRES:	20.01							
OWNER CODE 1:	Р							
OWNER CODE 2:								
OWNER CODE 3:								
HISTORIC SIGNI	FICANCE							
*DOE:		REGISTER NA	ME:					
*DOE DATE:			OPERTY NAME					
			CATEGORY:					
NOMINATION	N STATUS:	SIGNI	FICANCE LEVE	_ 1:	Ν	S	L	
DAT	E LISTED:	SIGNI	FICANCE LEVE	_ 2:	Ν	S	L	
	NUMBER:							
HISTORIC DISTRIC	TRATING: C or	NC CRITE	ERIA 1: A B	С	D			
	PERIOD:	CRITE	ERIA 2: A B	С	D			
		CRITE	ERIA 3: A B	С	D			
		CRITE	ERIA 4: A B	С	D			
SIGNIFICANCE NOT	ES:							

STRUCTURE DETAILS

* = REQUIRED FIELD



SHPO ID:			
*PROPERTY NAME:			
OTHER NAME:			
CURRENT FUNCTION:	Calving and cattle	FOUNDATION:	Poured concrete foundation
			Asphalt shingles over cedar
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	shingles
HISTORIC FUNCTION:	Livestock barn	ROOF SHAPE:	Gable
HISTORIC SUBFUNCTION:	Hay storage	STRUCTURAL SYSTEM:	Balloon framing
		STYLE:	Gable roof barn
OCCUPIED:	Yes	TYPE:	Livestock barn
ACCESSIBLE:	Yes with permission	WALLS:	2x4 studs with 1x6 #106 drop siding
STORIES:	2	SIGNIFICANT PERSON:	Andrew Norin
*DATE OF CONSTRUCTION:	About 1900	CULTURAL AFFILIATION:	?

ALTERED/MOVED NOTES: Original site. Any evidence of milk cow stanchions or horse stalls has been removed. Roof has been shingled with asphalt shingles. Has been converted into a barn for cattle. Has hay feed racks on the East and West walls to feed cattle in bad weather. There are trap doors in hayloft floor to lift up to fill hay feed racks below and then close to retain heat.

INTERIOR NOTES: <u>Has one row of 4" steel posts, with a 6 x 8 for a beam.</u> Floor joists are 2x6's. Has 4x6 sills.

OTHER NOTES: 2x4 stud walls with 1x6 #106 drop siding. Rafters are 2x6's. 1x8 bracing from top of wall in hayloft down to floor joists, 4' O.C. Has two galvanized metal ventilators on ridge of roof.


Windows are 8"x10" four light over 8"x10" four light in the East gable end. The balance of windows are 8"x10" four light.


*PHYSICAL NOTES: Barn is in good condition.

*UTM ZONE:	*RESTRICTED:	Υ	or	Ν
*UTM EASTING:				
*UTM NORTHING:				



SKETCH MAP





.





* = REQUIRED FIELD









PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone November 27, 2012

ROLL NUMBER: PHOTO NUMBER:


5 First floor, looking East, CAMERA DIRECTION: Feed rack on East wall






CAMERA DIRECTION: feed rack on West wall.









GARFIELD TWP.

O Farm & Home Publishers, Ltd.

23

CLAY CO., SD



HISTORY

This farm located in the SE 1/4 of Section 31, Glenwood Township, Clay County was homesteaded by Andrew Norin, August 24, 1870.

The 1894, 1901, 1912, 1924 and 1937 Clay County Atlas lists John Norin as the owner.

The 1948 Clay County Atlas lists Martha Norin as the owner.

The 1956 Clay County Atlas lists S. E. Norin as the owner.

Land was homesteaded by Andrew Norin on August 24, 1870. Andrew most likely built or had this barn built.

This farm became the Norin Century Farm on August 24, 1970. This farm has been in the Norin family for 142 years.