

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



SITE INFORMATION

*SURVEY DATE: July 26, 2012 *ADDRESS: 30631 458th Ave.
*SURVEYOR: Jim Stone *COUNTY: Clay
*CITY: Wakonda

LOCATION DESCRIPTION: From the intersection of South Dakota Highway 50 bi-pass and South Dakota Highway 19, North 9 miles to 308th Street, turn left (West) 4 miles to 458th Ave., turn right (North) about 1-3/4 mile, on the left (West) side.

LEGAL DESCRIPTION: NE 1/4, 24 - 94 - 53 Bethel Twp.

*QUARTER 1: NE 1/4
*QUARTER 2: _____
*TOWNSHIP: Bethel
*RANGE: 53
*SECTION: 24
ACRES: 158.72

OWNER NAME: Carol Jean Mayer
OWNER ADDRESS: 30631 458th Ave.
OWNER CITY: Wakonda
OWNER STATE: South Dakota
OWNER ZIP: 57073
QUAD NAME: _____

OWNER CODE 1: P
OWNER CODE 2: _____
OWNER CODE 3: _____

HISTORIC SIGNIFICANCE

*DOE: _____
*DOE DATE: _____
REASON INELIGIBLE: _____

REGISTER NAME: _____
MULTIPLE PROPERTY NAME: _____

NOMINATION STATUS: _____
DATE LISTED: _____
REFERENCE NUMBER: _____
HISTORIC DISTRICT RATING: C or NC
PERIOD: _____

CATEGORY: _____
SIGNIFICANCE LEVEL 1: N S L
SIGNIFICANCE LEVEL 2: N S L
CRITERIA 1: A B C D
CRITERIA 2: A B C D
CRITERIA 3: A B C D
CRITERIA 4: A B C D

SIGNIFICANCE NOTES: All steel oblong corncrib. 12'-6" wide x 51' long. Has six 10" vent tubes from floor through roof, equal spaced with swivel vents on roof to keep openings away from prevailing winds.

STRUCTURE DETAILS

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



SHPO ID: _____
 *PROPERTY NAME: _____
 OTHER NAME: _____

CURRENT FUNCTION: <u>Vacant</u>	FOUNDATION: <u>Poured concrete base</u>
CURRENT SUBFUNCTION: <u>Store shelled corn</u>	ROOF MATERIAL: <u>Steel panel roof</u>
HISTORIC FUNCTION: <u>Store ear corn</u>	ROOF SHAPE: <u>Gable with round ends</u>
HISTORIC SUBFUNCTION: <u>Store ear corn</u>	STRUCTURAL SYSTEM: <u>Steel angle iron studs and bracing</u>
	STYLE: <u>Oblong all steel corn crib</u>
OCCUPIED: <u>Yes</u>	TYPE: <u>Corn crib</u>
	WALLS: <u>Steel angle iron studs, perforated steel sidewalls</u>
ACCESSIBLE: <u>Yes with permission</u>	

STORIES: _____ SIGNIFICANT PERSON: August Friese
 *DATE OF CONSTRUCTION: Pre 1950's CULTURAL AFFILIATION: ?

ALTERED/MOVED NOTES: Original site.

INTERIOR NOTES: Poured concrete base with elevator gutter down the center. Short planks cover gutter and are removed as the bin is emptied. Has six 10" perforated ventilation tubes from the floor up through the roof. Swivel caps on the roof to keep the opening away from the prevailing wind.

OTHER NOTES: Wall studs and all cross bracing is angle iron. Outside covering is galvanized, perforated steel to allow for ventilation. Has four access doors on the West wall and a small access door on each end to start emptying the crib. This is a very unusual style of an all steel corncrib.

*PHYSICAL NOTES: Corncrib is in good condition. Carol Mayer called me July 25, 2012 and asked for this corncrib to be surveyed. She has hired a crew to dismantle it and haul it away on July 28th and July 29th, 2012. Carol Mayer claims that it is the only corncrib of its kind in South Dakota and there is only one in the state of Iowa.


*UTM ZONE: _____ *RESTRICTED: Y or N
 *UTM EASTING: _____
 *UTM NORTHING: _____

* = REQUIRED FIELD


**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**

SKETCH MAP

SKETCH MAP



PHOTOGR



* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: July 26, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: July 26, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: July 26, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SE, NE corner



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: July 26, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 4
CAMERA DIRECTION: Looking North, all steel studs and cross bracing, perforated steel sides

* = REQUIRED FIELD

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: July 26, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 5

CAMERA DIRECTION: Looking North, 10" perforated ventilation tubes, from floor through roof

HISTORY

This farm located, in the NE ¼ of section 24, Bethel Township, Clay County was homesteaded by Rasmus Jensen.

The 1894 and 1901 Clay County Atlas lists Rasmus Jensen as the owner.

The 1912, 1924, 1937 and 1948 Clay County Atlas lists August Friese as the owner.

The 1956 Clay County Atlas lists Elmer Friese as the owner.