


"SITE INFORMATION					
*SURVEY DATE:	May 16, 2013	*ADDRESS:	46685 301st Street		
*SURVEYOR:	Jim Stone	*COUNTY:	Clay		
		*CITY:	Beresford		
LOCATION DESCRIPTION: From Vermillion, the intersection of South Dakota Highway 50 bi-pass and					
University Road, North 17 miles to 301th Street, turn right, (East) about 1- 1/4 miles, on the right (South)					
side					
LEGAL DESCRIPTION: N	E ¼, 28– 95 – 51 (Glenwood Twp.			
*QUARTER 1: NE 1/4	4	OWNED NAME:	Daniel & Holly Hedeen		
QUARTER 2:	<u></u>	OWNER ADDRESS:	-		
*TOWNSHIP: Glenw	ood	OWNER CITY:			
*RANGE: 51		OWNER STATE:			
*SECTION: 28		OWNER ZIP:			
ACRES: 160.04	4	QUAD NAME:			
OWNER CODE 1: P					
OWNER CODE 2:					
OWNER CODE 3:					
HISTORIC SIGNIFICANO	CF.				
*505					
			REGISTER NAME:		
		MULTIPLE PR	OPERTY NAME:		
REASON INELIGIBLE:					
			CATEGORY:		
NOMINATION STATU	S:	SIGNII	SIGNIFICANCE LEVEL 1: N S L		
DATE LISTED:		SIGNII	SIGNIFICANCE LEVEL 2: N S L		
REFERENCE NUMBE	R:				
HISTORIC DISTRICT RATING	G: C or NC	CRITE	RIA1: A B C D		
PERIOD:		CRITE	RIA 2: A B C D		
			RIA 3: A B C D		
		CRITE	RIA 4: A B C D		
SIGNIFICANCE NOTES:					

STRUCTURE DETAILS




SHPO ID:						
*PROPERTY NAME:						
OTHER NAME:						
CURRENT FUNCTION:	Vacant	FOUNDATION:	Poured concrete			
CURRENT SUBFUNCTION:	Storage	ROOF MATERIAL:	Asphalt shingles over cedar shingles			
	o.o.u.go					
HISTORIC FUNCTION:	Ear corn and	ROOF SHAPE	Spire or cone shaped			
morekie i ekeriek.	gram storage	ROOT ONALE.	Masonary, solid and			
HISTORIC SUBFUNCTION:	Storage in alley	STRUCTURAL SYSTEM:	ventilating clay tile			
		STYLE:	Clay tile corn crib			
OCCUPIED:	Yes	TYPE:	Ear corn and grain elevator			
3333.123.			8-1/2" square solid			
	Yes with		and 8-1/2"square			
ACCESSIBLE:	permission	WALLS:	ventilating clay tile			
STORIES:	2	SIGNIFICANT PERSON:	C. W. Hoyer			
*DATE OF CONSTRUCTION:		CULTURAL AFFILIATION:	?			
			•			
ALTERED/MOVED NOTES: Original site. Asphalt shingles over the cedar shingles.						
-						
INTERIOR NOTES: First floo	or has a center 17'	diameter with a 10' alley on the North	and South sides with			
INTERIOR NOTES: First floor has a center 17' diameter with a 10' alley on the North and South sides with Inswing double doors. There is a wagon hoist to tilt wagons to unload into pit. There is a grain leg on the						
West side with grain cups 20" wide for grain or ear corn. The grain leg has sold by Oden Implement Vermillion, South Dakota and is painted on the side.						
· · · · · · · · · · · · · · · · · · ·						
OTHER NOTES: The center has a 12' high concrete and clay tile ceiling with a 17' diameter 30' tall grain						
bin above 17' center part. The area between the center circle and the 34' outer circle and above alleys on the North and South ends is the ear corn crib.						
the North and Count chas is t	ne car com cmb.					
*PHYSICAL NOTES: Corncrib and elevator is in very good condition.						
- 111 Olone No. 2011 Olin and olorator is in very good condition.						
*IITM 70NE.		*RESTRICTED: Y o	er N			
*UTM ZONE:		RESTRICTED: Y C	vi 1 1			
*UTM EASTING:						
*UTM NORTHING:						







SKETCH MAP



PHOTOGR





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: May 16, 2013 PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: May 16, 2013 PHOTO NUMBER: 2

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER:

DATE OF PHOTO: May 16, 2013 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: May 16, 2013 PHOTO NUMBER: CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone May 16, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, in center, looking NW, East wall of North alley and double

CAMERA DIRECTION: doors.



PHOTOGRAPHER:


Jim Stone DATE OF PHOTO: May 16, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, East side, looking up and NW into outer circle which is the

CAMERA DIRECTION: ear corn crib.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone May 16, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking up and SE, grain leg goes

CAMERA DIRECTION: up about 25'



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone May 16, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, East side, looking up and SE, outer circle which is the ear

CAMERA DIRECTION: corn crib...





PHOTOGRAPHER: Jim Stone May 16, 2013 DATE OF PHOTO:


ROLL NUMBER: PHOTO NUMBER:

9

First floor, East side, looking West, 8-1/2" x 8-1/2" ventilating hollow

CAMERA DIRECTION: clay tile.







HISTORY

This farm located in the NE ¼ of Section 28 in Glenwood Township, Clay County was homesteaded by John Johnson.

The 1894 and 1901 Clay County Atlas lists Carl Hoyer as the owner.

The 1912 Clay County atlas lists August Hoyer as the owner.

The 1924 Clay county Atlas lists Emma Hoyer as the owner.

The 1937 and 1948 Clay County Atlas lists C. W. Hoyer as the owner.

The 1956 Clay County Atlas lists Emma Hoyer as the owner.

