

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM



SITE INFORMATION

*SURVEY DATE: Aug. 14, 2012

*SURVEYOR: Jim Stone

*ADDRESS: 46868 304th Street

*COUNTY: Clay

*CITY: Beresford

LOCATION DESCRIPTION: South Dakota Highway 50, East two miles to Greenfield Road, turn left (North), 14-1/2 miles to 304th Street, turn right (East) about 1/2 mile, on the left (North) side.

LEGAL DESCRIPTION: SE 1/4, 2 – 94 – 51 Garfield Twp.

*QUARTER 1: SE 1/4

*QUARTER 2: _____

*TOWNSHIP: Garfield

*RANGE: 51

*SECTION: 2

ACRES: 157.07

OWNER CODE 1: P

OWNER CODE 2: _____

OWNER CODE 3: _____

OWNER NAME: John Eric Bylander

OWNER ADDRESS: 311 S. College Street

OWNER CITY: Carlisle

OWNER STATE: Pennsylvania

OWNER ZIP: 17013

QUAD NAME: _____

HISTORIC SIGNIFICANCE

*DOE: _____

*DOE DATE: _____

REASON INELIGIBLE: _____

REGISTER NAME: _____

MULTIPLE PROPERTY NAME: _____

CATEGORY: _____

NOMINATION STATUS: _____

DATE LISTED: _____

REFERENCE NUMBER: _____

HISTORIC DISTRICT RATING: C or NC

PERIOD: _____

SIGNIFICANCE LEVEL 1: N S L

SIGNIFICANCE LEVEL 2: N S L

CRITERIA 1: A B C D

CRITERIA 2: A B C D

CRITERIA 3: A B C D

CRITERIA 4: A B C D

SIGNIFICANCE NOTES: _____

STRUCTURE DETAILS

* = REQUIRED FIELD

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM



SHPO ID: _____

*PROPERTY NAME: _____

OTHER NAME: _____

CURRENT FUNCTION: Vacant

CURRENT SUBFUNCTION: Vacant

HISTORIC FUNCTION: Livestock barn

HISTORIC SUBFUNCTION: Hay and grain storage

FOUNDATION: Poured concrete

ROOF MATERIAL: Cedar shingles

ROOF SHAPE: Gable

STRUCTURAL SYSTEM: Balloon framing

Western feeder

STYLE: barn

OCCUPIED: No

TYPE: Livestock barn

ACCESSIBLE: Yes with permission

2x6, 1x6 car siding
& 1/2"x 6" cedar lap

WALLS: siding

STORIES: 2

SIGNIFICANT PERSON: John Bylander

*DATE OF CONSTRUCTION: Early 1900's

CULTURAL AFFILIATION: Swedish

ALTERED/MOVED NOTES: Original site. 30' x 36' lean-to added to the West side a long time ago.
Original siding was 1x6 car siding, no sheathing and 1x2"x6" cedar lap siding was added later, even on
the addition. Top part of the cupola gone.

INTERIOR NOTES: Has two rows 6x6 posts and a 6x6 for a beam. 2x8 floor joists. 10'x10' granary 16'
high is still in place in the SW corner of the main barn and a 10'x10' granary with a 10'x10' granary above
in the hay loft in the SE corner of the main barn. All of the horse stalls are still in place.

OTHER NOTES: Windows were 9"x12" four light. Walls are 2x6 with 1x6 car siding on all four walls and
1/2"x6" cedar lap siding was installed over that a long time ago. However the 30' x 36' addition on the
West side has 2x6 studs and 2x4 studs alternating on all three walls. Rafters are 2x6 except the West
lean-to where they are 2x12's 4' O.C. There is a row of 6x6 posts and a 6x6 beam supporting the center
of the 2x12 rafters. House was built in 1901.

*PHYSICAL NOTES: Barn is in fair condition. The roof is leaking. Needs roof re-roofed and repairs
on the doors.

*UTM ZONE: _____


*RESTRICTED: Y or N

*UTM EASTING: _____


*UTM NORTHING: _____

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM

SKETCH MAP




PHOTOGR



* = REQUIRED FIELD

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM

SKETCH MAP



PHOTOGR

* = REQUIRED FIELD

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: Aug. 14, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 1
CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: Aug. 14, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner

* = REQUIRED FIELD

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: Aug. 14, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: Aug. 14, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: Aug. 14, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 5
CAMERA DIRECTION: First floor, East lean-to,
looking NW, horse stalls



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: Aug. 14, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 6
CAMERA DIRECTION: First floor, center of
barn, looking NE, horse
stalls

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: Aug. 14, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 7

CAMERA DIRECTION: First floor, center of
barn, looking South, two
granaries on the South
end.



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: Aug. 14, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 8

CAMERA DIRECTION: First floor, West lean-to,
looking NW, 2x12 rafters
and 6x6's for support

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: Aug. 14, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 9

First floor, West lean-to,
looking NW, posts and
beam support of roof,
note 2x12 rafters 4' O.C.

CAMERA DIRECTION: _____



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: Aug. 14, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 10

Hayloft, looking South,
lower rafter bracing

CAMERA DIRECTION: _____

**SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE
HISTORIC SITES SURVEY STRUCTURE FORM**



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: Aug. 14, 2012

ROLL NUMBER: _____
PHOTO NUMBER: 11

CAMERA DIRECTION: Hayloft, looking South,
upper rafter bracing &
16' high granary in the
SW corner

SOUTH DAKOTA STATE HISTORIC PRESERVATION OFFICE

HISTORIC SITES SURVEY STRUCTURE FORM



T-94-N
GARFIELD DIRECTORY
(Residents - Owners or Renters)
GLENWOOD TWP.
R-51-W

464th AVE	UNIVERSITY AVE	466th AVE	467th AVE	GREENFIELD RD	469th AVE	470th AVE
303rd ST ■ Charles Strom 30346 6	■ Gordon R Johnson 30372 5	■ Christopher Kinsey 46629 4	■ C Carlson 30332 ■ Terry Jensen 46718 3	■ K Woltjer 30337 ■ Gavin Clark 30362 2	■ 46913 St ■ Leon Hansen 46975 1	303rd ST
304th ST ■ C Thedorff 46469 ■ Todd Johnson 30437 ■ Berg 30491 7	■ Orland Sterngquist 30472 ■ 46504 St 8	■ Merie Christensen 30404 ■ Nick Oyen 30396 9	■ Alden Lundquist 46733 10	■ M Schurch 30433 ■ 30438 Ave 11	■ Keith Kirkebæk 30415 ■ Kendal Frick 30474 12	304th ST
305th ST ■ Ryan Bear 30535 ■ B Erickson 46426 18	■ K Hansen 30512 ■ Brad Hansen 46502 17	■ Dean Lindstrom 30524 ■ Duane Lundquist 46636 16	■ Roland Gylfe 30534 ■ 46776 St 15	■ Randall Jensen 30540 ■ I Taylor 46820 14	■ Charles Jensen 30514 ■ 30536 Ave ■ Ron Larsen 30535 13	305th ST
306th ST ■ Don Lindstrom 30624 19	■ Brenden Richards 46501 ■ Marlon Olson 30692 ■ Spike 46534 20	■ 46507 St ■ Craig Nelson 30641 21	■ M Hamersma 46741 ■ Doug Hays 46767 22	■ Brian Jensen 46782 ■ Kendal Swice 46836 23	■ 46904 St ■ Roger Jensen 46958 24	306th ST
307th ST ■ Jerry Whelchel 46442 ■ L Hansen 46415 30	■ Scott Mollman 30717 ■ Richard Lind 30720 29	■ Mike Zwieter 30724 ■ James Danielson 30750 ■ Marvin Christensen 30766 28	■ S Hein 30768 ■ Jens Naglestad 46776 27	■ Kevin Colbert 46837 ■ Saur 46878 ■ Arlin Hansen 46880 26	■ Eric Alexander 46926 25	307th ST
308th ST ■ 42.9158 ■ 31 308th ST	■ Craig Jensen 30835 ■ Ballinger 30839 32	■ Larry Larson 30869 ■ David Alexander 30872 33	■ Curtis Fickbohm 30836 ■ 30879 Rd 34	■ Don Jensen 46825 ■ Reid Jensen 46829 35	■ Lamie 30834 ■ Bryce Jensen 30845 ■ David Howard 46970 36	308th ST
309th ST	■ Cort Nielsen 46548					309th ST

PRAIRIE CENTER TWP.

* = REQUIRED FIELD

HISTORY

This farm located in the SE ¼ of Section 3, Garfield Township, Clay county was homesteaded by Erick R. Mepler.

The 1894, 1902, and 1912 Clay County Atlas lists Erick Messler as the owner.

The 1924 Clay County Atlas lists Oscar Messler as the owner.

The 1937 Clay County Atlas lists D. M. Bylander as the owner and J. M. Johnson as the operator (renter).

The 1948 and 1956 Clay County Atlas lists Dan Bylander as the owner.