

"S ITE INFORMATION					
*SURVEY DATE: June	e 5, 2013 *ADDRESS:	29835 460 th Ave.			
*SURVEYOR: Jim	Stone *COUNTY:	Clay			
	*CITY:	Centerville			
LOCATION DESCRIPTION: From	m Vermillion, the intersection of Sou	th Dakota Highway 50 bi-pass and			
South Dakota Highway 19, North18 miles to 299th Street, turn left, (West) about 2 miles to 460th Ave., turn					
right (North) about 1/2 mile, on the left (West) side.					
LEGAL DESCRIPTION: NE ¼, 8 – 95 – 52 Riverside Twp.					
*QUARTER 1: <u>N 1/4</u>	OWNER NAME:	Boyd Ostrem			
*QUARTER 2:	OWNER ADDRESS:	29545 460 th Ave.			
*TOWNSHIP: Riverside	OWNER CITY:	Centerville			
*RANGE: <u>52</u>	OWNER STATE:	South Dakota			
*SECTION:8	OWNER ZIP:	57014			
ACRES: 172.80	QUAD NAME:				
OWNER CODE 1: P					
OWNER CODE 2:					
OWNER CODE 3:					
HISTORIC SIGNIFICANCE					
	DECISTED NA	ME.			
*DOE DATE:	MULTIPLE DD	REGISTER NAME: MULTIPLE PROPERTY NAME:			
REASON INELIGIBLE:	MULTIPLE PR	OPERIT NAME.			
REASON INELIGIBLE.					
		CATEGORY:			
NOMINATION STATUS:	SIGNII	FICANCE LEVEL 1: N S L			
		FICANCE LEVEL 2: N S L			
REFERENCE NUMBER:					
HISTORIC DISTRICT RATING: C		RIA1: A B C D			
PERIOD:	CRITE	RIA 2: A B C D			
		RIA 3: A B C D			
	CRITE	RIA 4: A B C D			
SIGNIFICANCE NOTES:					


STRUCTURE DETAILS



SHPO ID:				
*PROPERTY NAME:		-		
OTHER NAME:				
CURRENT FUNCTION:	Vacant	FOUNDATION:	Poured concrete	
CURRENT SUBFUNCTION:	Vacant	ROOF MATERIAL:	Asphalt shingles over cedar shingles	
HISTORIC FUNCTION:	Corn crib and grain elevator	ROOF SHAPE:	Gothic round roof	
HISTORIC SUBFUNCTION:	Corn crib and grain elevator	STRUCTURAL SYSTEM:		
		STYLE:	Gothic round roof grain elevator	
OCCUPIED:	Yes	TYPE:		
ACCESSIBLE:	Yes with permission	WALLS:	2x10, 2x8 and 2x6 studs with spaced 1x 4's	
ACCESSIBLE.	permission	WALLS.	1845	
STORIES:	3	SIGNIFICANT PERSON:	Margaret Smith	
*DATE OF CONSTRUCTION:	1920's ? CU	LTURAL AFFILIATION:	German	
ALTERED/MOVED NOTES: Original site. Steel roofing has been installed over cedar shingles on the roof. One sliding door has fallen off on the South side. Grain pit has been filled in and concreted over.				
INTERIOR NOTES: 2x8 stud	s 12" O. C. 11' high on e	ach side of 12' wide alley. 3x1	2 joists 12" O. C. with	
double 3x12"s 24" O. C. above alley for floor of granaries above. 2x8 studs 12"O. C. up 17' for sides walls				
access to move elevator spou	it to different granaries of the contract of the contract of the center of each of the contract of the contrac	ross bracing above granaries vor ear corncribs. Two walls of 2 ch 12' crib. These walls have 1 ar corn.	2x6 studs 24" O. C. x	
OTHER NOTES: The East and West exterior walls are 2x8 studs 12" O. C. 14'-7" tall. They have a 6x8 sill				
and (3) 2x12's for a top plate.	These walls and the inte	erior walls in the alley have spa	aced 1x4's applied	
diagonally. The gable end wa	ills are 2x10 studs 12" O	. C. 14' – 6" high with a 6x8 sill	and (3) 2x12's for a	
plate. Another wall of 2x10 st	uds 12" O. C., is on top ters. The gable ends ha	of the first wall and has (2) $2x1$, ve diagonal sheathing with $\frac{1}{2}$ "	2's for a plate. 2x10s	
*PHYSICAL NOTES: Barn is in good condition.				
*UTM ZONE:		*RESTRICTED: Y o	or N	
*IITM EASTING.				
*IITM NORTHING:				




SKETCH MAP





SKETCH MAP



PHOTOGR





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 5, 2013

ROLL NUMBER: PHOTO NUMBER:

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 5, 2013 **ROLL NUMBER:**

PHOTO NUMBER:

CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: June 5, 2013 PHOTO NUMBER: 3
CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 5, 2013 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 5, 2013

ROLL NUMBER: PHOTO NUMBER:

5

First floor, looking SW, grain leg going up and down on West wall of

CAMERA DIRECTION: alley



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 5, 2013

ROLL NUMBER: PHOTO NUMBER:

First floor, looking up and SW, 3x12 floor joists above alley for granaries above, note every other

CAMERA DIRECTION: joist is doubled.





PHOTOGRAPHER: DATE OF PHOTO: June 5, 2013

Jim Stone

ROLL NUMBER: PHOTO NUMBER:

Ventilation alley, looking North, bracing to support

CAMERA DIRECTION: walls from caving in.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 5, 2013

ROLL NUMBER: PHOTO NUMBER:

Ventilation alley, looking North, bracing to prevent wall from caving in, Note 3x12 floor joists supporting granaries

CAMERA DIRECTION: above alley.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 11, 2013

ROLL NUMBER: PHOTO NUMBER:

Third floor, looking up and SW, top of grain leg, drop to fill cribs and bins, note Meyer Mfg.Co. Morton, ILL.

CAMERA DIRECTION:



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: June 5, 2013

ROLL NUMBER: PHOTO NUMBER:

10

Third floor, looking up and East, peak and gable

CAMERA DIRECTION: end of cupola.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 5, 2013

ROLL NUMBER: PHOTO NUMBER:

Third floor, looking SW, grain leg, both up and down, note Gunderson Imp. Co. Centerville, S.

CAMERA DIRECTION: Dak.



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 5, 2013

ROLL NUMBER: **PHOTO NUMBER:**

12

Third floor, large cast iron sprocket drive wheel

CAMERA DIRECTION: for grain leg.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 5, 2013

ROLL NUMBER: PHOTO NUMBER:

13

Four floor, Baldor commerical electric motor, this plate was on the back side, took picture to read, but flash

CAMERA DIRECTION: glare covered specs.





PHOTOGRAPHER: Jim Stone DATE OF PHOTO: June 5, 2013


ROLL NUMBER: PHOTO NUMBER:

14

Third floor, looking South, South gable end, note double laminate rafters for wall on

CAMERA DIRECTION: cupola.





© Farm & Home Publishers, Ltd.

35

CLAY CO., SD



HISTORY

This farm located in the NE ¼ of Section 8, Riverside Township, Clay County was homesteaded by Issac Jones.


The 1894, 1901, 1912, and 1924 Clay County Atlas lists Margaret Smith as the owner.

The 1937 Clay County Atlas lists Mary Paddock as the owner.

The 1948 and 1956 Clay County Atlas lists Orin Paddock as the owner.

The following is from -

Centerville Dakota Territory - Sunshine State 1883 - 1983 A Century of Memory



W. H. Smith



W. H. Smith was born in Coblenz, Germany, on March 10, 1837. He came to the United States when he was 18 years old. He soon enlisted as a private in Company L, First Regiment and re-enlisted on Jan. 5, 1864, and served the entire period of the Civil War. He was mustered out of the Army as a corporal at Austin Texas.

He returned to Iowa where he married Margaret Brimmer. They lived at Bellevue, Iowa, until 1879 when the family moved to Bloomingdale, D. T. and a year later moved to Riverside Twp., where they worked on the Prentis and Lee ranch for three years and then purchased their own farm southwest of Centerville where they lived until they retired and moved to Centerville.

After the death of his wife in 1921 Mr. Smith returned to the farm and lived with his daughter, Mrs Orrin Paddock, until her death in 1925. The remainder of his life was spent in Beresford with a niece where he died in 1929.

Five children were born to the Smiths. Margaret married Edward McElroy and spent most of her life on a farm near Dallas, S. D. She is buried with her husband in the Catholic Cemetery at Dallas. The rest of her brothers and sisters are all buried with their parents at Riverside Cemetery, Centerville. Margaret had 10 children, five of whom are still living.

Joseph died at the age of seven. Mary was a teacher and only lived to be 29. John, single, lived until 1934. He worked in Omaha, Nebr.

Anna was born Feb. 25, 1876 and married Orrin Paddock.

Facts on this ear corn crib and Elevator By Jim Stone

Each side of this ear corn crib would hold 3800 bushels of ear corn if filled to a height of 20'. This would be a total of 7600 bushels of ear corn. I think that with the bracing that is in this structure it could be filled to 25', which would add 1000 more bushels on each side. This makes the total capacity 9600 bushels.

The granaries above the driveway are two bins 12'x 20' x 17' tall and one bin 7'x 8'x 17' tall. These three bins have the capacity when filled level to 17' deep, of 7200 bushels of grain or shelled corn.

The amount of dimension lumber in this structure just staggers the imagination! 2x10 stud walls 12" O. C., 36' by up to 36' tall on the North and South walls. Two 2x8 stud walls 12" O. C., 14'- 7" tall by 48' long and two more 2x8 stud walls 12" O. C., 28' tall by 48' long. Four 2x6 stud walls 24" O. C., 18' – 10" tall by 48' long. Triple 2x12 plates on top of first floor, double 2x12 plates on top of second floor. 220 feet of 6" x 8" sills and massive amounts of 2x8 and 2x10 bracing. 72 pieces of 3x13 x 14' bridge plank for floor joists, to support the granaries above driveway. Massive amounts of 1x 4 to cover walls and ventilation alleys.

