

"SITE INFORMATION


*SURVEY DATE:	June 10,2	2010	*ADDRESS:	33030	404	A	/e.			
*SURVEYOR:	Jim Sto	ne	*COUNTY:	Union)					
			*CITY:	Jeffer	son,	Sou	uth [Dako	ta	
LOCATION DESCRIPTION:	Goina sa	outh on intersta	ite 29. turn off at	the Jeff	erso	n ex	cit. t	urn le	eft e	ast
Into Jefferson to the first sto	p sign, tu	rn right on old	highway 77, 2-1							
left, north, about 2-1/2 miles	, on the ric	jht, east side o	f the road.							
LEGAL DESCRIPTION:F				he NW 1	⁄₄ of	Sec	tion	21, .	Jeffe	rson
Township, 90 N, Range 48 w	est of the	5 th P.M. Union	County							
				Thoma		hno	.	۸ امد		lina
*QUARTER 1: SW 1	/4		OWNER NAME:	Thoma Orear	is Jo	mns			•	iina
*QUARTER 2:	<u> </u>	owi	IER ADDRESS:		484 th	Ave				
*TOWNSHIP: Jefferso	n		OWNER CITY:							
*RANGE: 48		C	WNER STATE:							
*SECTION: 21			OWNER ZIP:							
ACRES: 10			QUAD NAME:							
OWNER CODE 1: P										
OWNER CODE 2:										
OWNER CODE 3:										
	~ =									
HISTORIC SIGNIFICANO	<u>CE</u>									
*DOE:			REGISTER NA	ME:						
*DOE DATE			MULTIPLE PR	OPERT	Y NA	ME:				
REASON INELIGIBLE:										
				C	ATE	GOF	RY:			
						\/Fi	1.	N	S	L
NOMINATION STATU	S:		SIGNI	FICANC	E LE	VEL				_
NOMINATION STATU DATE LISTE				FICANCI FICANCI					S	L
	D:								S	L
DATE LISTE REFERENCE NUMBE	D: R:	NC	SIGNII		E LE	VEL	. 2:	N	S	L
DATE LISTE REFERENCE NUMBE HISTORIC DISTRICT RATIN	D: R: G: C or	NC	SIGNII	FICANC	E LE A	VEL B	2: C	N D	S	Ĺ
DATE LISTE REFERENCE NUMBE HISTORIC DISTRICT RATIN	D: R: G: C or		SIGNII CRITE CRITE	FICANCI	E LE A A	VEL B B	. 2: C C	N D D	S	Ĺ
DATE LISTE REFERENCE NUMBE HISTORIC DISTRICT RATIN	D: R: G: C or		SIGNII CRITE CRITE CRITE	FICANCI ERIA 1: ERIA 2:	E LE A A A	VEL B B	. 2: C C	N D D	S	Ĺ
DATE LISTE REFERENCE NUMBE HISTORIC DISTRICT RATIN PERIO	D: R: G: C or D:		SIGNII CRITE CRITE CRITE	FICANCI RIA 1: RIA 2: RIA 3: RIA 4:	E LE A A A	VEL B B B	C C C C	N D D D	S	Ĺ
DATE LISTE REFERENCE NUMBE HISTORIC DISTRICT RATIN PERIO	D: R: G: C or D:		SIGNII CRITE CRITE CRITE	FICANCI RIA 1: RIA 2: RIA 3: RIA 4:	E LE A A A	VEL B B B	C C C C	N D D D	S	L
DATE LISTE REFERENCE NUMBE HISTORIC DISTRICT RATIN	D: R: G: C or D:		SIGNII CRITE CRITE CRITE	FICANCI RIA 1: RIA 2: RIA 3: RIA 4:	E LE A A A	VEL B B B	C C C C	N D D D	S	Ĺ




STRUCTURE DETAILS

5	SHPO ID:						
*PROPERT	Y NAME:						
OTHE	R NAME:						
CURRENT FU	NCTION:	Storage		FOUNDA	TION:	Poured concrete	
CURRENT SUBFUN	CTION:	Storage		ROOF MATE	RIAL:	Asphalt roofing	
HISTORIC FU	NCTION:	Dairy and cattle		ROOF SH	IAPE:	Gable roof	
HISTORIC SUBFU	NCTION:	Hay and silage	s	TRUCTURAL SYS	TEM:	Balloon framing	
				S	ΓYLE:	Gable roof barn	
ОС	CUPIED:	Yes		7	ГҮРЕ:	Dairy barn	
		Yes with				2x6 studs, 1x6 drop	
ACCE	SSIBLE:	permission	W	ALLS:		siding.	
;	STORIES:	2	SIGNIFI	CANT PERSON:	M. C	C. Davis	
*DATE OF CONSTR	RUCTION:	1908 -1909	CULTURA	L AFFILIATION:		?	
ALTERED/MOVED N	NOTES:	Roof has asphalt sl	hingles, wall	s and roof extens	ion arc	ound two silos on	
the east side. All st	anchions	have been remove	d. (8) 36" x	4'-7" windows hav	ve alun	ninum storms.	
		ded on the south ex					_
suggests that the ov	wners aui	t the dairy or down	sized the da	irv and added bee	ef cattle	e. Addition added to	_
the east end 46' x 2							
NTERIOR NOTES	B#****	! 11 11		San da Landa (d. Inc. dl.	41		
		m in the southwest					
					all nay	feed racks have been	_
		nd the east 52' of th					
						O.C. to support (5)	
						Two rows of (4) 2x8	
• • • • • • •			•		•	he exterior wall down	
to the floor, with 2x		(see drawings) 2x6		D.C. with 1x12 spa	iced ro	of sheathing.	
		n good condition, e					
*PHYSICAL		on enclosing silos is owners are going to					
NOTES:		el roofing.		*RESTRICTED:	Υ 0	r N	
				KEOTKIOTED.			
*IITM NODTUNG:							
OTIVI NORTHING:							
"SITE INF	ORMAT	TION					
·							
*UTM EASTING:							
*UTM NORTHING:							













PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 10, 2018 PHOTO NUMBER: 1

CAMERA DIRECTION: Looking NE, SW corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 10, 2018 PHOTO NUMBER: 2
CAMERA DIRECTION: Looking NW, SE corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: DATE OF PHOTO: June 10, 2018 PHOTO NUMBER: 3

CAMERA DIRECTION: Looking SW, NE corner



PHOTOGRAPHER: Jim Stone ROLL NUMBER:
DATE OF PHOTO: June 10, 2018 PHOTO NUMBER: 4
CAMERA DIRECTION: Looking SE, NW corner





PHOTOGRAPHER: Jim Stone ROLL NUMBER: 5
DATE OF PHOTO: June 10, 2018 PHOTO NUMBER: 5
CAMERA DIRECTION: Looking SE, cupolas



PHOTOGRAPHER:	Jim Stone	ROLL NUMBER:			
DATE OF PHOTO:	June 10, 2018	PHOTO NUMBER:	6		
		Looking north east, most recent			
		milking parlor			





PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: June 10, 2018

ROLL NUMBER: PHOTO NUMBER:

Looking north west, gutter in concrete floor

in milking parlor **CAMERA DIRECTION:**



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 10, 2018

ROLL NUMBER: PHOTO NUMBER:

Looking west, enclosed stairs to hayloft in

CAMERA DIRECTION: milking parlor





PHOTOGRAPHER: DATE OF PHOTO: June 10, 2018

Jim Stone

ROLL NUMBER: PHOTO NUMBER:

Looking SE on first floor,5 2x12's posts, 5 -2x12's beam, 2x 6 angle

CAMERA DIRECTION: braces, 2x10 joists



PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: June 10, 2018

ROLL NUMBER: PHOTO NUMBER:

Looking north east, on first floor, south wall

CAMERA DIRECTION: enclosing milking parlor

* = REQUIRED FIELD





PHOTOGRAPHER: Jim Stone
DATE OF PHOTO: June 10, 2018

ROLL NUMBER: PHOTO NUMBER:

11

Looking north east, one of the wood stave silos CAMERA DIRECTION: _ in the east side of barn



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: June 10, 2018

ROLL NUMBER: PHOTO NUMBER:

12

Looking south east 4 ply 2x8 posts with 2x8

CAMERA DIRECTION: <u>bracing</u> in hayloft





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 10, 2018

ROLL NUMBER: PHOTO NUMBER:

Looking south east, 3x8 brace from wall down to CAMERA DIRECTION: floor, 2x8 angle bracing



PHOTOGRAPHER:

Jim Stone DATE OF PHOTO: June 10, 2018

ROLL NUMBER: PHOTO NUMBER:

Looking west in hayloft, large door for lifting

CAMERA DIRECTION: hay into hayloft.





PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 10, 2018

ROLL NUMBER: PHOTO NUMBER:

15

Looking north east, in hayloft, hay slings still hanging from hay track

CAMERA DIRECTION:



PHOTOGRAPHER: DATE OF PHOTO:

Jim Stone June 10, 2018


ROLL NUMBER: PHOTO NUMBER:

16

Looking south east, 2 feet of south silo concrete foundation above grade and 3'

CAMERA DIRECTION: below grade







HISTORY

This farm changed owners several times.

This farm is located - SW 1/4 of NW 1/4, Section 21, T90n- R48W of the 5th PM

Deed 1-369: United states to Edwin E. Parker. Receipt for \$200.00 (11/19/1870)

Deed 1-670: Edwin E. Parker & Nellie Parker to Andrew L. Walls for \$1,200.00 (03/18/1871)

Deed 2-367: United States to Edwin E. Parker, Patent (07/24/1872)

Deed 10-34: A. L. Walls and Julia A Walls to M. C. Davis for \$1,500.00 (04/18/1883)

Deed 16-235: M. C. Davis & Harriet R. Davis to D. A. Williams & E. R. Smith for \$11,000.00 (03/24/1891)

Deed 17-525: D. A. William & Lizzie H. Williams and E. R. Smith & Angie E. Smith to Union Loan & Trust Co. (05/06/1892)

Deed 19-423: Union County Sheriff to M. C. Davis for \$1,800.00 (10/09/1895)

Deed 36-510: M. C. Davis & May J. Davis to: Trustees of Iowa College (12/05/1916)

Deed 33-635: Trustees of Iowa College to The Grinnell College Foundation for \$66,500.00 (04/07/1917)

Deed 33-368: Trustees of Iowa College to The Grinnell College Foundation (04/21/1917)

Deed 37-166: The Grinnell College Foundation to H. L. Craven for \$77,200.00 (03/07/1919)

Deed 37-167: H. L. Craven & Emma M. Craven to P. W. Lewis for \$83,575.00 (03/08/1919)

Deed 41-483: P. W. Lewis & Laura D. Lewis to The Trustees of Iowa College (03/04/1927)

Deed 52-353: Trustees of Iowa College: Carl E. Fornia, Alva L. Fornia, Harold L. Fornia & Gladys M. Fornia for \$56,000.00 (03/03/1953)